

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)205 Braddell Road
Singapore 579701

Tel: 63837613 Fax: 62815767/65462533 Email: teokeejin@cdge.com.sg

INSURER: **India International Insurance Pte Ltd (HQ)****PARTICULARS OF CLAIM**

Claim Type:	OD (Own Damage)	Ref. No:	
Policy No:	D20MFL0000326_02	Date of Loss:	27/07/2022
Vehicle Reg. No.:	SMM5392M	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	COMFORTDELGRO RENT-A-CAR PTE LTD		

Make/Model:	MITSUBISHI OUTLANDER, 2.0 (A)	Vehicle Reg. Date:	08/02/2021
Vehicle Colour:	Red		
Engine No:	4J11BC9359	Chassis No:	GF7W0601641
Odometer:	35232 KM		

Paint Type:
List Item Discount: 10.00 %
Total Loss? **NO**
Est. Duration of Repair (day) 9

Present Location: COMFORTDELGRO ENGINEERING PTE LTD (BRADDELL)

COST OF CLAIMS

	Amount
Parts	8,019.22
Miscellaneous Items	101.00
Labour	3,550.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	11,670.22
+ GST 7.00% (\$\$)	816.92
Nett Amount (\$\$)	12,487.14

This claim is handled by: PATRICK TIA JEE KIANG*Generated using Merimen e-Claims Internet Estimation & Adjusting System*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 04 Aug 2022)
Parts:	M1-SUV	mitsubishi OUTLANDER 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	ComfortDelGro Engineering Pte Ltd/SMM5392M/04/08/2022 09:33	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT LH FENDER	10.00	0.00	*537.00 FL
2	1		*FRT LH FENDER WHEELARCH GARNISH	10.00	0.00	*158.00 FL
3	1		*FRT LH DR SIDE MIRROR ASSEMBLY	10.00	0.00	*550.00 FL
4	1		*FRT LH DR SIDE MIRROR COVER	10.00	0.00	*128.00 FL
5	1		*FRT LH DOOR	10.00	0.00	*881.00 FL
6	1		*FRT LH DOOR GLASS	10.00	0.00	*353.00 FL
7	1		*FRT LH DOOR GLASS MOULDING	10.00	0.00	*149.00 FL
8	1		*FRT LH DR STICKER (BLACK)	10.00	0.00	*41.00 FL
9	1		*FRT LH DR WHEATHERSTRIP	10.00	0.00	*168.00 FL
10	1		*FRT LH DR HANDLE	10.00	0.00	*93.00 FL
11	1		*FRT LH DR HADBLE SEAL 1	10.00	0.00	*6.00 FL
12	1		*FRT LH DR HANDLE SEAL 2	10.00	0.00	*6.00 FL
13	1		*FRT LH DR HANDLE SWITCH	10.00	0.00	*263.25 FL
14	1		*FRT LH DR HINGE TOP	10.00	0.00	*42.00 FL
15	1		*FRT LH DR HINGE LOWER	10.00	0.00	*42.00 FL
16	1		*FRT LH DR CHECKER	10.00	0.00	*38.00 FL
17	1		*FRT LH DOOR LOCK	10.00	0.00	*322.00 FL
18	1		*FRT LH DOOR STICKER	10.00	0.00	*20.00 FL
19	1		*FRT LH DOOR OUTER MOULDING	10.00	0.00	*130.00 FL
20	1		*REAR LH DOOR	10.00	0.00	*851.00 FL
21	1		*REAR LH DR GLASS MOULDING	10.00	0.00	*113.00 FL
22	1		*REAR LH DR STICKER 1 (BLACK)	10.00	0.00	*42.00 FL
23	1		*REAR LH DR STICKER 2 (BLACK)	10.00	0.00	*72.00 FL
24	1		*REAR LH DR WHEATHERSTRIP	10.00	0.00	*161.00 FL
25	1		*REAR LH DR HANDLE	10.00	0.00	*93.00 FL
26	1		*REAR LH DR HANDLE SEAL 1	10.00	0.00	*6.00 FL
27	1		*REAR LH DR HANDLE SEAL 2	10.00	0.00	*6.00 FL
28	1		*REAR LH DR HINGE TOP	10.00	0.00	*42.00 FL
29	1		*REAR LH DR HINGE LOWER	10.00	0.00	*42.00 FL
30	1		*REAR LH DR CHECKER	10.00	0.00	*37.00 FL
31	1		*REAR LH DOOR LOCK	10.00	0.00	*321.00 FL
32	1		*REAR LH DOOR STRICKER	10.00	0.00	*20.00 FL
33	1		*REAR LH DOOR OUTER MOULDING	10.00	0.00	*130.00 FL
34	1		*REAR LH FENDER	10.00	0.00	*1,298.00 FL
35	1		*REAR LH WHEELARCH GARNISH	10.00	0.00	*160.00 FL
36	1		*REAR FUEL DOOR	10.00	0.00	*77.00 FL
37	1		*REAR LH QUATER GLASS	10.00	0.00	*713.00 FL
38	1		*REAR BUMPER	10.00	0.00	*799.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	8,910.25
- List Item Discount on L Items (S\$)	891.03
Total Parts (S\$)	8,019.22

ComfortDelGro Engineering Pte Ltd/SMM5392M/04/08/2022 09:33. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	FRT LH FENDER INNER SHIELD CLIP	30.00
2	1	REAR BUMPER CLIP	30.00
3	1	REAR LH FENDER INNER SHIELD CLIP	30.00
4	1	OD/TP Case (Insurer)	11.00
Sub Total (\$\$)			101.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	To knock & straighten on accident area, to remove & refit damage parts	New	1,600.00
2	To putty & respray on LH side affected area	New	1,400.00
3	To check wiring	New	50.00
4	To remove & refit FRT LH Door trim, door glass, window regulator, door lock to assist work load	New	100.00
5	To remove & refit REAR LH Door trim, door glass, window regulator, door lock to assist work load	New	100.00
6	To remove & refit REAR LH quarter glass.	New	100.00
7	To remove & refit inner seat & upholstery to assist work load	New	100.00
8	To remove & refit petrol tank to assist work load.	New	100.00
Gross Labour Cost (\$\$)			3,550.00

ComfortDelGro Engineering Pte Ltd/SMM5392M/04/08/2022 09:33. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >