



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTOMOTIVE ENGRG. & MGT. DIVISION (TP)			Ref:	CS/SPF22007546/Ece2
ACCIDENT CLAIMS SECTION (SPORE POLICE FORCE) POLICE LOGISTICS BASE (PLB) 1			Date:	20/10/2022
HEMMANT ROADSINGAPORE 438675				
ATTN: HAFIZUL FARHAN BIN RAHMAT			Code:	SPF
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	QX 2013Y	Veh. Inspected	SFD 992U	
Policy No.		Coverage (\$)	0.00	
Claim No.	ACS/105/009/2022/049	Excess (\$)	0.00	
Assign From	HAFIZUL FARHAN BIN RAHMAT	Assign Date	08/08/2022	
2. Vehicle Particulars & Condition				
Make & Model	AUDI Q3	c.c	1395	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	WAUZZZ8U4GR032932	Colour	SILVER	
Odometer	91080 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	235/50 R18	PIRELLI	4 mm	
L/H Front Tyre	235/50 R18	PIRELLI	4 mm	
R/H Rear Tyre	235/50 R18	PIRELLI	4 mm	
L/H Rear Tyre	235/50 R18	PIRELLI	4 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	05/08/2022	Inspection Date	10/08/2022	
Survey held at	24 BENOI SECTOR SINGAPORE 629857			
Repairer	PREMIUM AUTOMOBILES PTE LTD			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.				
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			11 Working Days	