## COMFORTDELGRO ENGINEERING PTE LID

**REPAIR ESTIMATE\*** 

VEHICLE NO

SHA5704U

MAKE

REG 30.08.2017

MODEL

PRIUS G4

30.07.2022

Qty	Parts Description/ Labour		CHIANG /NTUC		
	Descriptiony Labour	Type	Unit Price	Amount	
	FRONT BUMPER ASSY				
10	FRONT BUMPER CLIP			\$586.18	
1	FRONT UNDER COVER			\$2.20	
-	FRONT BUMPER BRACKET LH			\$180.80	
:	FRONT RADIATOR GRILLE EMBLEM		.7.	\$77.00	
	FRONT BUMPER HOLE LH		y. vi	\$88.00	
	FRONT HEADLAMP ASSY LH	,	are	\$2,735.28	
	FRONT FOG LAMP LH			\$2,733.20	
	FRONT FENDER SHIELD LH		NY -	× \$198.50	
	1 FRONT FENDER EMBLEM LH			× \$86.20	
	SUB TOTAL		2757.20	\$4,272.54	
	25.00%		2757.28 2067.96	\$1,068.13	
	DISCOUNTED TOTAL		2067.96	\$3,204.40	
į	FRONT FENDER ADVERTISEMENT		w	\ \$100.00	
	Labour Charge			\$100.00	
	Panel Beating		25	10 40-5 0-	
	Spray Painting Charge		52	\$850.00	
	Towing Fee		L An	\$600.00	
	Reset front wheel alignment		, AVA	\$60.00	
	Check Wiring & Lighting		630	\$60.00	
	TOTAL LABOUR			\$60.00	
	. O TAL LABOUR		2697.96	\$1,630.0	
-	ESTIMATE TOTAL		2697.96 415\$2150 22lays *	\$4,934.40	
			2 days		
	his is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will				
	be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

Tanfehn 97495749)
WP, 118/22 R 430pm
o 2 days
cls Resny affer report
faufth Clhhando: wn

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer Signature