

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM \_\_\_\_\_

### THIRD PARTY EXPRESS SETTLEMENT (C)

Vehicle No:	SLH3219H (Insd veh)	Model:	BMW 318I 1.5 SEDAN LED NAV
	SLR6633Y (TP veh)		(A)
Date of Accident:	06/08/2022		

Global Sum Settlement	:	[ ] Yes	[ X ] No	
Repair Estimate	: \$			<b>9,019.50</b>
Final Repair Cost	: \$			5,500.00
Loss of Use	: \$			days at \$0.00 per day
Rental (if any)	: \$			300.00    3 days
LTA / GIA Search Fee	: \$			0.00
Others:	: \$			0.00
	: \$			
Final Settlement Sum	: \$			5,800.00

Is Third Party Workshop GIA Registered?		[ ] YES	[ X ] NO	(Kindly indicate below)
A) For <b>Non GIA Registered Workshop:</b>		Agreed Liability _____ 100 _____ (%)		
B) For <b>GIA Registered Workshop:</b>		BOLA Applicable: Yes/ No    BOLA Scenario No: _____		
BOLA Liability: _____ (%)		Assessed Liability (*): _____ (%)		
<i>* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.</i>				
Remarks _____				

Payment Instruction: Payee's Breakdown			
1)	YSK Auto Workshop	: \$	5,800.00
2)		: \$	

JOANNE LEE KHANG MIN

\_\_\_\_\_  
LKK Auto Consultants Pte Ltd

29 Nov  
2022

\_\_\_\_\_  
Date

**Please attach all the supporting documents to the form.**

**(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))**