



簡福星噴漆工廠  
KAN FOOK SING MOTOR WORKSHOP

61 Defu Lane 12, Singapore 530147

Tel : (65) 6747 9560, 6858 2126, 6858 4361

Fax : (65) 6748 1006, 6281 8428

E-mail: kanfs@pacific.net.sg • Website: www.carparts.com.sg

Business Reg No: J21468-026

GST Reg No: M9-0005333-E

INSURER: **ERGO Insurance Pte. Ltd. (HQ)**

**PARTICULARS OF CLAIM**

|                               |                                                             |                       |                   |
|-------------------------------|-------------------------------------------------------------|-----------------------|-------------------|
| Claim Type:                   | OD (OWN DAMAGE)                                             | Ref. No:              |                   |
| Policy No:                    | DMFG22005172                                                | Date of Loss:         | 05/08/2022        |
| Vehicle Reg. No.:             | SLC719C                                                     | Driveable?            |                   |
| Driver Age/Info:              |                                                             | Party At Fault:       | UNKNOWN           |
| TP Injury Involved?           | YES                                                         | Third Party Involved? | YES               |
| Insured/Claimant:             | HWA SENG BUILDER PTE LTD                                    |                       |                   |
| Make/Model:                   | NISSAN NOTE, 1.2 (A)                                        | Vehicle Reg. Date:    | 29/04/2016        |
| Vehicle Colour:               | METALLIC GREY                                               |                       |                   |
| Engine No:                    | HR12185104B                                                 | Chassis No:           | JN1TAAE12Z0972254 |
| Odometer:                     | 0 KM                                                        |                       |                   |
| Paint Type:                   |                                                             |                       |                   |
| Total Loss?                   | <b>NO</b>                                                   |                       |                   |
| Est. Duration of Repair (day) | 15                                                          |                       |                   |
| Description of Accident/Loss  | REMARK : RPICE MIGHT BE DIFFREENT DUT TO STOCK AVAILABILITY |                       |                   |
| Present Location:             | KAN FOOK SING MOTOR WORKSHOP (DEFU)                         |                       |                   |

| <b>COST OF CLAIMS</b>               | <b>Amount</b>    |
|-------------------------------------|------------------|
| Parts                               | 16,703.50        |
| Miscellaneous Items                 | 120.00           |
| Labour                              | 1,370.00         |
| Paintwork Labour                    | 1,200.00         |
| Towing                              | 0.00             |
| <b>Calculated Gross Total (S\$)</b> | <b>19,393.50</b> |
| <b>- Excess (S\$)</b>               | <b>600.00</b>    |
| <b>(S\$)</b>                        | <b>18,793.50</b> |
| <b>+ GST 7.00% (S\$)</b>            | <b>1,315.55</b>  |
| <b>Nett Amount (S\$)</b>            | <b>20,109.05</b> |

**This claim is handled by: MT TAN**

Generated using Merimen e-Claims Internet Estimation & Adjusting System

## REPAIR DETAILS

### Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 08 Aug 2022)

Parts: 144 NISSAN NOTE 1.2 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Kan Fook Sing Motor Workshop/SLC719C/08/08/2022 15:32

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

### Estimates on Parts

| No. | Qty | Part No. | Particulars                            | %Disc      | %Depr | Amount      |      |
|-----|-----|----------|----------------------------------------|------------|-------|-------------|------|
| 1   | 1   |          | *STEERING AIR BAG                      | act ✓ 0.00 | 0.00  | *1,500.00 F | ✓    |
| 2   | 1   |          | *STEERING AIR BAG WIRE                 | act ✓ 0.00 | 0.00  | *180.00 F   | ✓    |
| 3   | 1   |          | *DASHBOARD<br>NO STOCK                 | de ✓ 0.00  | 0.00  | -           |      |
| 4   | 1   |          | *DASHBOARD AIR BAG                     | act ✓ 0.00 | 0.00  | *2,200.00 F | ✓    |
| 5   | 1   |          | *AIR BAG ECU<br>NO STOCK               | act ✓ 0.00 | 0.00  | 1400.00     |      |
| 6   | 1   |          | *AIR BAG SENSOR RH                     | act ✓ 0.00 | 0.00  | *350.00 F   | ✗ nn |
| 7   | 1   |          | *AIR BAG SENSOR LH                     | act ✓ 0.00 | 0.00  | *350.00 F   | 600  |
| 8   | 1   |          | *SEAT BELT RH                          | act ✓ 0.00 | 0.00  | *600.00 F   | ✓    |
| 9   | 1   |          | *SEAT BELT LH                          | ? 0.00     | 0.00  | *600.00 F   | ✗ nn |
| 10  | 1   |          | *FRONT WIPER CORNER GARNISH RH         | ? 0.00     | 0.00  | *30.00 F    | ✗ nn |
| 11  | 1   |          | *FRONT WIPER CORNER GARNISH LH         | ? 0.00     | 0.00  | *30.00 F    | ✗ nn |
| 12  | 1   |          | *FRONT BONNET                          | bt ✓ 0.00  | 0.00  | *450.00 F   | ✓    |
| 13  | 1   |          | *FRONT BONNET LOCK                     | bt ✓ 0.00  | 0.00  | *80.00 F    | ✓    |
| 14  | 1   |          | *FRONT BONNET HINGE RH                 | bt ✓ 0.00  | 0.00  | *45.00 F    | ✓    |
| 15  | 1   |          | *FRONT BONNET HINGE LH                 | bt ✓ 0.00  | 0.00  | *45.00 F    | ✓    |
| 16  | 1   |          | *FRONT BONNET STOPPER RH               | mis ✓ 0.00 | 0.00  | *30.00 F    | 15   |
| 17  | 1   |          | *FRONT BONNET STOPPER LH               | mis ✓ 0.00 | 0.00  | *30.00 F    | 15   |
| 18  | 1   |          | *FRONT SUPPORT PANEL                   | bt ✓ 0.00  | 0.00  | *250.00 F   | ✓    |
| 19  | 1   |          | *FRONT SUPPORT GARNISH                 | de ✓ 0.00  | 0.00  | *180.00 F   | ✓    |
| 20  | 1   |          | *FRONT LOWER MEMBER                    | ? 0.00     | 0.00  | *220.00 F   | ✗ nn |
| 21  | 1   |          | *FRONT FENDER RH                       | bt ✓ 0.00  | 0.00  | *320.00 F   | ✓    |
| 22  | 1   |          | *FRONT FENDER LH                       | bt ✓ 0.00  | 0.00  | *320.00 F   | ✓    |
| 23  | 1   |          | *FRONT FENDER SHIELD RH                | de ✓ 0.00  | 0.00  | *95.00 F    | ✗ nn |
| 24  | 20  |          | *FRONT FENDER SHIELD CLIP              | mis ✓ 0.00 | 0.00  | *50.00 F    | 40   |
| 25  | 1   |          | *FRONT FENDER 1/4 GLASS MOULDING RH    | ? 0.00     | 0.00  | *200.00 F   | ✗ nn |
| 26  | 1   |          | *FRONT FENDER 1/4 GLASS MOULDING LH    | ? 0.00     | 0.00  | *200.00 F   | ✗ nn |
| 27  | 1   |          | *FRONT GRILLE                          | act ✓ 0.00 | 0.00  | *210.00 F   | ✓    |
| 28  | 1   |          | *FRONT EMBLEM                          | act ✓ 0.00 | 0.00  | *50.00 F    | 55   |
| 29  | 1   |          | *FRONT HEADLAMP RH                     | act ✓ 0.00 | 0.00  | *1,200.00 F | 450  |
| 30  | 1   |          | *FRONT HEADLAMP LH                     | act ✓ 0.00 | 0.00  | *1,200.00 F | 450  |
| 31  | 1   |          | *FRONT BUMPER                          | de ✓ 0.00  | 0.00  | *350.00 F   | ✓    |
| 32  | 1   |          | *FRONT BUMPER SIDE RETAINER RH         | de ✓ 0.00  | 0.00  | *30.00 F    | ✓    |
| 33  | 1   |          | *FRONT BUMPER SIDE RETAINER LH         | 0.00       | 0.00  | *30.00 F    | ✓    |
| 34  | 1   |          | *FRONT BUMPER FOAM<br>NO STOCK         | act ✓ 0.00 | 0.00  | 150-        |      |
| 35  | 1   |          | *FRONT BUMPER REINFORCEMENT            | bt ✓ 0.00  | 0.00  | *250.00 F   | ✓    |
| 36  | 1   |          | *FRONT BUMPER REINFORCEMENT BRACKET RH | bt ✓ 0.00  | 0.00  | *220.00 F   | 185  |
| 37  | 1   |          | *FRONT BUMPER REINFORCEMENT BRACKET LH | bt ✓ 0.00  | 0.00  | *220.00 F   | 185  |
| 38  | 1   |          | *FRONT BUMPER TOW COVER<br>NO STOCK    | act ✓ 0.00 | 0.00  | 35 -        |      |
| 39  | 10  |          | *FRONT BUMPER CLIP                     | act ✓ 0.00 | 0.00  | *25.00 F    | ✓    |
| 40  | 1   |          | *HORN                                  | ? 0.00     | 0.00  | *80.00 F    | ✗ nn |
| 41  | 1   |          | *AIR CON CONDENSER                     | bt ✓ 0.00  | 0.00  | *480.00 F   | 125  |
| 42  | 1   |          | *AIR CON LIQUID PIPE                   | ? 0.00     | 0.00  | *120.00 F   | ✗ nn |



| No. | Qty | Part No. | Particulars               |       | %Disc | %Depr | Amount    |          |
|-----|-----|----------|---------------------------|-------|-------|-------|-----------|----------|
| 43  | 1   |          | *AIR CON SUCTION HOSE     | ✓ bt  | 0.00  | 0.00  | *250.00 F | 100 (sn) |
| 44  | 1   |          | *AIR CON DISCHARGE HOSE   | ✓ bt  | 0.00  | 0.00  | *250.00 F | 100 (sn) |
| 45  | 1   |          | *RADIATOR                 | ✓ bt  | 0.00  | 0.00  | *380.00 F | ✓        |
| 46  | 1   |          | *RADIATOR HOSE TOP        |       | 0.00  | 0.00  | *40.00 F  | X nn     |
| 47  | 1   |          | *RADIATOR HOSE LOWER      |       | 0.00  | 0.00  | *40.00 F  | X nn     |
| 48  | 1   |          | *RAIDATOR TOP MOUNTING RH |       | 0.00  | 0.00  | *25.00 F  | X nn     |
| 49  | 1   |          | *RAIDATOR TOP MOUNTING LH |       | 0.00  | 0.00  | *25.00 F  | X nn     |
| 50  | 1   |          | *RADIATOR FAN ASSY        | ✓ cra | 0.00  | 0.00  | *320.00 F | ✓        |
| 51  | 1   |          | *SPARE TANK               | ✓ de  | 0.00  | 0.00  | *70.00 F  | ✓        |
| 52  | 1   |          | *WASHER TANK              | ✓ de  | 0.00  | 0.00  | *125.00 F | ✓        |
| 53  | 1   |          | *INTAKE MANIFOLD          |       | 0.00  | 0.00  | 600 -     | cra ✓    |
|     |     |          | NO STOCK                  |       |       |       |           |          |
| 54  | 1   |          | *AIR CLEANER BOX          |       | 0.00  | 0.00  | 330-      | cra ✓    |
|     |     |          | NO STOCK                  |       |       |       |           |          |
| 55  | 1   |          | *AIR CLEANER HOSE         | ✓ dm  | 0.00  | 0.00  | *150.00 F | 140      |
| 56  | 1   |          | *ALTERNATOR               |       | 0.00  | 0.00  |           | xnn      |
|     |     |          | NO STOCK                  |       |       |       |           |          |
| 57  | 1   |          | *ENGINE MOUNTING RH       | bt ✓  | 0.00  | 0.00  | *195.00 F | 180      |
| 58  | 1   |          | *ENGINE MOUNTING LH       |       | 0.00  | 0.00  | *85.00 F  | X nn     |
| 59  | 1   |          | *ENGINE MOUNTING RR       |       | 0.00  | 0.00  | *80.00 F  | X nn     |
| 60  | 1   |          | *FRONT SIDE MIRROR RH     |       | 0.00  | 0.00  | *330.00 F | X nn     |

F=Franchise part.

|                                     |           |
|-------------------------------------|-----------|
| Sub Total (\$\$)                    | 15,185.00 |
| + Margin on L,N Items 10.00% (\$\$) | 1,518.50  |
| Total Parts (\$\$)                  | 16,703.50 |

Kan Fook Sing Motor Workshop/SLC719C/08/08/2022 15:32. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

## Estimates on Miscellaneous Items

| No                         | Qty | Particulars                   | Amount       |
|----------------------------|-----|-------------------------------|--------------|
| <u>Miscellaneous Items</u> |     |                               |              |
| 1                          | 1   | FRONT FENDER 1/4 GLASS GUM LH | ? 40.00 X nn |
| 2                          | 1   | FRONT FENDER 1/4 GLASS GUM RH | ? 40.00 X nn |
| 3                          | 1   | FRONT NUMBER PLATE            | mis 40.00 ✓  |
| Sub Total (S\$)            |     |                               | 120.00       |

## Estimates on Labour

| No                      | Particulars                                                                      | Lab.Type   | Amount   |
|-------------------------|----------------------------------------------------------------------------------|------------|----------|
| <u>Paintwork Labour</u> |                                                                                  |            |          |
| 1                       | SPRAYPAINTING CHARGES                                                            | New ✓ 1100 | 1,200.00 |
| <u>Labour Items</u>     |                                                                                  |            |          |
| 2                       | TO CHECK WIRING SYSTEM                                                           | New ✓ 30   | 50.00    |
| 3                       | TO REMOVE/REFIT/REFILL AIR CON GAS                                               | New ✓ ✓    | 100.00   |
| 4                       | TO REMOVE/REFIT DASHBOARD                                                        | New ✓ 200  | 240.00   |
| 5                       | TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS | New ✓ 800  | 980.00   |
| Gross Labour Cost (S\$) |                                                                                  |            | 2,570.00 |

Kan Fook Sing Motor Workshop/SLC719C/08/08/2022 15:32. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Taufik 97495749 / 62563561

Not Authorise, Revert

Ex: 600

10/8/22 @ 1pm

Resurvey before paint

Taufik @ Lkhankun

09 days.

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
  - To display damaged part(s) during resurvey
  - Parts prices are subject to confirmation
  - Third party survey is on a "Without Prejudice" basis
  - No illegal modification(s) is allowed
  - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: