



簡福星摩多工廠

KAN FOOK SING MOTOR WORKSHOP

Headquarter: Blk 8 JTC Defu Industrial City #04-29 Defu South Street 1, Singapore 533758

Tel: (65) 6747 9560, 6743 5344 • Fax: (65) 6748 1006

E-mail: ryan@kanfs.net / patricia@kanfs.net

Branch: 1 Kaki Bukit Avenue 6 #01-13, Singapore 417883

Tel: (65) 6481 5150 • Fax: (65) 6481 8683

(SUPPLEMENTARY)

INSURER: **ERGO Insurance Pte. Ltd. (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	DMFG22005172	Date of Loss:	05/08/2022
Vehicle Reg. No.:	SLC719C	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	YES	Third Party Involved?	YES
Insured/Claimant:	HWA SENG BUILDER PTE LTD		
Make/Model:	NISSAN NOTE, 1.2 (A)	Vehicle Reg. Date:	29/04/2016
Vehicle Colour:	GREY		
Engine No:	HR12185104B	Chassis No:	JN1TAAE12Z0972254
Odometer:	154765 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	15		
Description of Accident/Loss	REMARK : RPICE MIGHT BE DIFFREENT DUT TO STOCK AVAILABILITY		
Present Location:	KAN FOOK SING MOTOR WORKSHOP (DEFU)		

COST OF CLAIMS

	Amount
Parts	715.00
Miscellaneous Items	0.00
Labour	0.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$)	715.00
+ GST 7.00% (\$)	50.05
Nett Amount (\$)	765.05
+ Previous Estimates (\$)	20,109.05
Claim Total (\$)	20,874.10

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 24 Oct 2022)**Parts:** 144 NISSAN NOTE 1.2 (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** Kan Fook Sing Motor Workshop/SLC719C/24/10/2022 15:53**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT FENDER SIDE BRACKET RH	0.00	0.00 bt ✓	*40.00 F
2	1		*FRONT CHASSIS BRACKET SIDE RH	0.00	0.00 bt ✓	*50.00 F
3	1		*RADIATOR TOP SEAL	0.00	0.00 dis ✓	*50.00 F
4	1		*CONDENSER SUDE GARNISH	0.00	0.00 de ✓	*55.00 F
5	1		*FRONT FENDER TOP COVER RH	0.00	0.00 de ✓	*40.00 F
6	1		*FAN BELT	0.00	0.00 cut ✓	*50.00 F
7	1		*AIR CLEANER BOX LOWER	0.00	0.00 cra ✓	*320.00 F
8	1		*RADIATOR SIDE SEAL	0.00	0.00 dis ✓	*45.00 F

F=Franchise part.

Sub Total (\$\$)	650.00
+ Margin on L,N Items 10.00% (\$\$)	65.00
Total Parts (\$\$)	715.00

Kan Fook Sing Motor Workshop/SLC719C/24/10/2022 15:53. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

There are no labour items selected.

Kan Fook Sing Motor Workshop/SLC719C/24/10/2022 15:53. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >