

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	AXA INSURANCE	PTE LTD		Ref:	CS3/ASM22007587/Tcy3m4	
	8 SHENTON WAY SINGAPORE 0688		Date:	26/09/2022		
	ATTN: ANG YVON	NE		Code:	ASM	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SMP 1560E	Veh. Inspected	k	SLZ 6624G	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	S2M048CZ	Excess (\$)		0.00	
	Assign From	ANG YVONNE	Assign Date		10/08/2022	
2.	2. Vehicle Particulars & Condition					
	Make & Model	HONDA CIVIC 1.6	c.c		1595	
	Engine No.	HIDDEN	Year of Reg.		2009	
	Chassis No.	JHMFD46209S200182	Colour		WHITE	
	Odometer	164640 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	205/55 R16	DUNLOP		6 mm	
	L/H Front Tyre	205/55 R16	DUNLOP		6 mm	
	R/H Rear Tyre	205/55 R16	DUNLOP		6 mm	
	L/H Rear Tyre	205/55 R16	DUNLOP		6 mm	
4.	Description of Damages					
	THE VEHICLE SUS	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT & REAR PORTION.				
5.	5. General Information					
	Accident Date	07/08/2022	Inspect Date /	Time	10/08/2022 (02:00 PM)	
	Survey held at GARAGE 13 PTE LTD					
	8 KAKI BUKIT AVE 4 #03-46 PREMIER 415875 SINGAPORE.					
5a.	5a. Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$14,000-\$16,000					
5b. Estimate Days of Repair						
	ESTIMATED NOR	ESTIMATED NORMAL PERIOD FOR REPAIR: 14 Working Days				

Report Ref No. CS3/ASM22007587/Tcy3m4

Inspected By

MOHAMAD TAUFIKH

K.K.LAU CPT(RET)

M.MATAI, AMSAE-A BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.