10/12/22, 9:32 AM Preview

NOTE: TO BE COMPLETED BY SURVEYOR

TF/	NA A		

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:		SGX6171R (Insd veh)		Model:	Model:		KIA FORTE K3 1.6 SX (A)		
	SLC3707S (TP veh) 07/08/2022								
of Accident:									
10 0 111		I							
	nt :	[] Yes							
Final Repair Cost									
Loss of Use						4.00 days at \$60.00 per day			
• • • •							days		
/ GIA Search Fee	!				2.00				
ers:					0.00				
			: \$						
Settlement Sum			: \$	4	2,810.00				
nird Party Works	hop GIA	Registered?	[]	YES	[X]	NO	(Kindly indicate below)		
For Non GIA Re	gistered	Workshop:		Agreed I	_iability	100	(%)		
For GIA Registe	red Wor	kshop:		BOLA A	pplicable:	Yes/ No	BOLA Scenario No:		
BOLA Liability: _		(%)		Assesse	d Liability	(*):	(%)		
* Assessed Liabi	lity to be	filled only for ch	ain coll	isions and t	or cases v	vhere BO	LA does not apply.		
arks									
ment Instruction	: Payee'	s Breakdown							
Tan Lim Motor F	te Ltd				: \$		2,810.00		
					: \$				
					: \$				
l.									
				12 ∩α	t				
JOANNE LEE KHAN		NG MIN	IN		2022				
LKK Auto C	onsultan	ts Pte Ltd		Date					
	al Sum Settlement air Estimate I Repair Cost of Use all (if any) I GIA Search Feeters: I Settlement Sum hird Party Works For Non GIA Registe BOLA Liability: * Assessed Liability: arks ment Instruction Tan Lim Motor F	al Sum Settlement : air Estimate Repair Cost of Use GIA Search Fee Restlement Sum For Non GIA Registered Wor BOLA Liability: * Assessed Liability to be arks Tan Lim Motor Pte Ltd JOANNE LEE KHA	SLC3707S (TP veh) of Accident: 07/08/2022 al Sum Settlement : [] Yes air Estimate Repair Cost of Use al (if any) / GIA Search Fee ars: Settlement Sum aird Party Workshop GIA Registered? For Non GIA Registered Workshop: For GIA Registered Workshop: BOLA Liability:(%) * Assessed Liability to be filled only for charks ment Instruction: Payee's Breakdown	SLC3707S (TP veh) of Accident: of Accident: of Accident: of O7/08/2022 all Sum Settlement : [] Yes air Estimate : \$ Repair Cost : \$ of Use : \$ all (if any) : \$ GIA Search Fee : \$ ars: : \$ Settlement Sum : \$ Ind Party Workshop GIA Registered? For Non GIA Registered Workshop: For GIA Registered Workshop: BOLA Liability:(%) * Assessed Liability to be filled only for chain colliarks ment Instruction: Payee's Breakdown Tan Lim Motor Pte Ltd JOANNE LEE KHANG MIN	SLC3707S (TP veh) of Accident: 07/08/2022 all Sum Settlement : [] Yes	SLC3707S (TP veh) of Accident: 07/08/2022 all Sum Settlement : [] Yes	SLC3707S (TP veh) for Accident: 07/08/2022 all Sum Settlement : Yes [X No air Estimate : \$ 6,730.51 Repair Cost : \$ 2,568.00 of Use : \$ 240.00 4.00 all (if any) : \$ 0.00 GIA Search Fee : \$ 2.00 ars: : \$ 0.00 Settlement Sum : \$ 2,810.00 Settlement Sum : \$ 2,810.00 Settlement Sum Settlement Sum		

Please attach all the supporting documents to the form. (Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/Bill (if any)

about:blank 1/1