

Jin Auto Services Pte Ltd

Blk 14 Defu Lane 10 #01-412

Singapore 539195

Tel: 62898126 Fax : 62870590

Email: Jin@jinauto.com.sg

Company Reg No:200704370C GST Reg No :200704370C

8/8/2022

M/S GREAT AMERICAN INSURANCE

DEAR SIR/MADAM

ESTIMATE REPAIR COST FOR TOYOTA RAV4 - SJW40U

DOA: 07/08/2022

S/N	QTY	DESCRIPTION		
1	1 PC	FRONT BUMPER	\$	X 250.00
2	10 PCS	FRONT BUMPER CLIPS	\$	X 18.00
3	1 PC	FRONT LH FENDER	\$	bt 360.00
4	1 PC	FRONT LH FENDER TRIM GARNISH	\$	de 72.00
5	1 PC	FRONT LH FENDER PROTECTOR	\$	de 38.00
6	1 PC	FRONT LH MUDFLAP	\$	cut 58.00
7	1 PC	FRONT LH DOOR	\$	bt 680.00
8	1 PC	FRONT LH DOOR LH LOWER HINGE	\$	? 42.00
9	1 PC	FRONT LH DOOR PROTECTOR	\$	cut 146.00
10	1 PC	FRONT LH FENDER SHIELD	\$	de 114.00
12	1 PC	FRONT LH SHOCK ABSORBER	\$	bt 234.00
13	1 PC	FRONT LH DRAG LINK	\$	? 78.00
14	1 PC	FRONT LH ABS SENSER WIRE	\$	? 198.00
15	1 PC	FRONT LH KNUCKLE ARM	\$	bt 264.00
16	1 PC	FRONT LH KNUCKLE BEARING	\$	bt 222.00
17	1 PC	FRONT LH DRIVE SHAFT	\$	? 816.00
18	1 PC	FRONT LH LOWER ARM	\$	bt 210.00
19	1 PC	FRONT LH LOWER ARM BALL JOINT	\$	? 84.00
20	1 PC	FRONT LH CHASSIS MEMBER	\$	X REPAIR
21	1 PC	FRT POWER STEERING RACK & PINION	\$	bt 2340.00
				<u>6224.00</u>

disassemble
photo
for u/c

Jin Auto Services Pte Ltd

Blk 14 Defu Lane 10 #01-412

Singapore 539195

Tel: 62898126 Fax : 62870590

Email: Jin@jinauto.com.sg

Company Reg No:200704370C GST Reg No :200704370C

8/8/2022

M/S NTUC INCOME

DEAR SIR/MADAM

ESTIMATE REPAIR COST FOR TOYOTA RAV4 - SJW40U

DOA: 07/08/2022

S/N	QTY	DESCRIPTION		
22		REAR LH DOOR	\$	RY REPAIR
23		REAR LH DOOR PROTECTOR	\$	mis 96.00
24		LH LOCKER PANEL	\$	REPAIR
			\$	6320.00
		Add 15%	\$	948.00
			\$	7268.00
25		TOWING FEE	\$	✓ 80.00
26		RENEW UNDERCARRIAGE	\$	photo 180 450.00
27		WHEEL ALIGNMENT	\$	✓ 80.00
28		SPRAY PAINTING	\$	660 1180.00
29		LABOUR CHARGE	\$	600 780.00
30		FRONT LH TYRE	\$	
31		FRONT LH RIM	\$	
32		TUFF COAT	\$	30 100.00
33		WIRING	\$	x 35.00
			\$	9973.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total

Tanfah 9749 5749/62563561

'wp' Not Authorise, Revert

Ex: to be advise 11/8/22.

tanfah@lkkauto.com.

6 days

Resurvey before / after fault

To check if / or ptp repair