



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
INDIA INTERNATIONAL INSURANCE PL 64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711			Ref: CS/III22007618/Kcy3 Date: 11/08/2022 Code: III2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	Veh. Inspected	SMY 6064R	
	Policy No. D18MFL0003414_03	Coverage (\$)	0.00	
	Claim No.	Excess (\$)	0.00	
	Assign From Bhargavi Purushothaman Dhanya	Assign Date	11/08/2022	
2. Vehicle Particulars & Condition				
	Make & Model	c.c	0	
	Engine No. HIDDEN	Year of Reg.		
	Chassis No.	Colour		
	Odometer -	Steering		
	Brakes	Modification		
	General			
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre			mm
	L/H Front Tyre			mm
	R/H Rear Tyre			mm
	L/H Rear Tyre			mm
4. Description of Damages				
5. General Information				
	Accident Date 19/07/2022	Inspection Date	11/08/2022	
	Survey held at COMFORTDELGRO ENGINEERING PTE LTD 205 BRADDELL ROAD BLK C, 3RD FLOOR SINGAPORE 579701.			
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			