

SIN HWEE MOTOR PTD LTD

BLK 3023A UBI RD 1 #01-59
SINGAPORE 408717
UEN: 201327079M

LKK Auto Consultants		Estimate	
the Repairer of the following:			
Date	Estimate #		
10/8/2022	1013		
- To resurvey before/after spray painting - To display damaged part(s) during resurvey - Parts prices are subject to confirmation - Third party survey is on a "Without Prejudice" basis - No illegal modification(s) is allowed - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company			
Acknowledged by Repairer			
Signature:			
Date:			

Name / Address
LOH WEE MENG

TPAXA
Asher

ZNE100399113

VEHICLE NO	MODEL
SJH 952 S	TOYOTA WISH

Description	Qty	Rate	Total
REAR BUMPER <i>Deltd</i>	2	845.90	845.90 585
SIDE RETAINER <i>for</i>		50.20	100.40
END PANEL <i>Deltd</i>		527.60	527.60
WEATHER STRIP <i>cut</i>		299.30	299.30
END PANEL TOP GARNISH <i>new</i>		245.00	245.00
BOOTLID <i>Reps</i>		985.77	985.77
WINDSCREEN MOULDING <i>new</i>		210.60	210.60
INNER LOCK <i>new</i>		309.45	309.45
CENTER LOGO <i>for</i>		43.77	43.77
EXHAUST BOX <i>Deltd</i>		735.99	735.99
SUBTOTAL			4,303.78
LESS 20% <i>25%</i>		-860.75	-860.75
BUMPER CLIP <i>new</i>	10	4.50	45.00 30
REVERSE SENSOR <i>Deltd</i>		280.00	280.00 20
TO SUPPLY FITTINGS AND INSTALL REVERSE SENSOR		80.00	80.00 50
TO REMOVE AND REFIX REAR WINDSCREEN		150.00	150.00
TO SUPPLY WINDSCREEN SEALANT		80.00	80.00
TO REMOVE AND REFIX INNER TRIMS, SEATS AND BOARDS		150.00	150.00 60
TO DISMOUNT AND ALIGN EXHAUST BOX		180.00	180.00 80
TO TRANSFER BOOTLID MECHANISMS AND FITTINGS TO NEW BOOTLID		150.00	150.00
TO REPLACE END PANEL INCLUDE KNOCKING, CUTTING AND WELDING		950.00	950.00 60
TO REPLACE AND ALIGN AFFECTED PARTS TO SYMMETRICAL SPEC.		950.00	950.00 60
TO SPRAY PAINT REAR BOOTLID, BUMPER, FLOORBOARD AND END PANEL		950.00	950.00 60
TO SUPPLY AND TUFF KOTE		150.00	150.00 60
TO CARRY OUT WIRE CHECKING		80.00	80.00 30

Adrian
w/s 12/08/22

OSRys

Total

Total 3429.04 \$6,688.03

L/s: 27K