

ESTIMATED

GBG2358U PEUGEOT

No	Qty	DESCRIPTION	DATE	08.08.2022	AMOUNT S\$
1	1	FRONT BONNET bt			2,127.00
2	1	RADIATOR GRILLE TOP PANEL Xan			1,073.00 X
3	1	RADIATOR TOP GRILLE Xan			1,125.00 X
4	1	RADIATOR TOP GRILLE (LOGO) Xan			298.00 X
5	1	RADIATOR SUPPORT PANEL bt			1,655.00 480
6	1	FRONT BUMPER REINFORCEMENT Xan			1,120.00 X
7	1	FRONT BUMPER bt			1,813.00 120
8	2	FRONT BUMPER FOG LAMP COVER bt 1pc			598.00 280
9	1	FRONT BUMPER LOWER GRILLE bt			917.00 330
10	2	FRONT BUMPER LOWER GRILLE MOULDING R+L Xan			570.00 X
11	1	FRONT BUMPER SIDE RETAINER LH bt RH			660.00 86
12	1	FRONT HEADLAMP PANEL RH bt			255.00 429
13	1	FRONT FENDER RH bt			98.00
14	1	FRONT FENDER COVER RH bt			89.00 35
15	1	FRONT FENDER SIGNAL LAMP RH bt			285.00 X
16	1	FRONT FENDER UNDER LINER LH Xan			955.00 X
17	1	FRONT FENDER INNER PANEL LH Xan			952.00 140
18	1	WIPER WASHER TANK C/W MOTOR bt			45.00 X
19	1	WASHER TANK FUNNEL Xan			2,500.00 X
20	1	POWER STEERING PUMP Xan			850.00 X
21	1	FRT SHOCK ABSORBER LH Xan			640.00 200
22	2	WHEEL RIM repair RH LH 1pc			\$ 19,965.00
		LESS 10%			\$ 1,996.50
					\$ 17,968.50

No	Qty	DESCRIPTION	SPECIAL NETT ITEM	AMOUNT S\$
1	1	FRONT HEADLAMP RH bt		1360 2,250.00
2	1	FRONT NUMBER PLATE W/CASE Xan		40.00 X
3	2	TYRE 185/60/15 Xan		210.00 420.00 X
				\$ 2,710.00

LABOUR & MISCELLANEOUS:

No	LABOUR & MISCELLANEOUS:	AMOUNT S\$
1	To remove damaged body parts with all necessary components/attachments apply hot-works where necessary repair, reshape body dented panels in accordance with factory specifications replace new parts refit and align into position refit all necessary components/attachments	1,600.00 800
2	To spray paint replaced/repared body parts inclusive of preparatory works and painting materials	1,000.00 600
3	To remove,refix- radiator,air con condenser with all necessary components/ attachments to faciliate repair work	250.00 80
4	To conduct headlamp alignment	30.00
5	To remove,replace power steering pump with all necessary attachments	250.00 Xan
6	To conduct front wheel alignment	80.00 60
7	To remove,replace wiper washer tank with all necessary attachments	60.00 40

To apply anti rust solution on affected areas

1670

~~4060~~
\$ 3,350.00

LIST PARTS	\$ 17,968.50
SN PARTS	\$ 2,710.00
LABOUR	\$ 3,350.00
	\$ 24,028.50

Rene

Hp 90010068

7 days

45

12/08/22 @ 1530

Resurvey after repair

Resurveyed alignment

copy

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

4061.70

1560.00

1670.00

7291.70

202

5833.36

112-451800 / 17 damp