

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way  
#09-16  
Singapore 079120

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn:

Date: 12 Aug 2022

## **Preliminary Advice**

Vehicle No	: SJL3700L	Accident Date	: 10/08/2022
Make	: AUDI A4	Policy No.	: 2100488648-05
Assignment Date	: 12/08/2022	Excess	: S\$0.00
Date of Inspection	: 12/8/2022	Est. Duration of Repair	: 21
Inspection At	: PREMIUM AUTOMOBILES PTE LTD		

### **Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	77,491.00
Revised Amount	:S\$	48,597.00
Check Items (Estimated)	:S\$	17,728.00
Total	:S\$	66,325.00
Lump Sum Repair	:S\$	

### **Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	86,000.00
COE / PARF Rebate	:S\$	41,215.00
Salvage Value	:S\$	
Margin for Repair	:S\$	44,785.00

### **Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments :Please note that the preliminary advise amount (Revised & Check items) stated are subject to consistency check, part prices and labour cost .