

12/6 19/09

dealer

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2285269)



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax: 63449773

116, Alexandra Road
Sime Darby Business Centre
Singapore 159944
FAX: 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Page No. : 1 of 5

Estimate No. : b1 62884
Date Estimated : 12/08/2022
Prepared By : Jack Ng Guo Ming

- ESTIMATE REPAIR FOR -
Daniel Seah
100 Gerald Drive
#01-84
Singapore 798592

- ACCOUNT - 135
China Taiping Insurance (S) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLR8989H	WBA12AK0207H36866	29/09/2021	218i Gran Coupe	15

DESCRIPTION	VALUE
To replace front bumper and front left fender.	1275 / 2,250.00
To respray front bumper and left front fender.	1826 / 1,923.00
To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct check for proper function.	168 / 177.00
To check electrical wiring system and lighting	168 / 177.00
To replace left headlight.	456 / 481.00
To check steering geometry and conduct wheel alignment in accordance with BMW specifications. (1x).	X 531.00
To replace tyre and wheel rim including balancing. (1x).	X 94.00
Sundries.	80 / 150.00
Total Labour 1:	5,783.00

DESCRIPTION	QTY	PRIC	VALUE
ALLOY RIM 7.5JX17 DOUBLE SPK 548 X nn	1	996.90	996.90
FRT LH SIDE PANEL X R	1	639.70	639.70
LH FOG LAMP COVER / cut (black)	1	47.30	47.30
FRT BUMPER BOTTOM TRIM PANEL ? X nn	1	177.00	177.00
LH AIR INLET FINISHER ? X nn	1	68.95	68.95
LH GRID LATERAL ? X nn	1	80.80	80.80
FRT FLAP TOWING EYE PRIMED X nn	1	43.95	43.95
FRT BUMPER PANEL PRIMED (PDC/PMA) X nn	1	929.20	929.20
SET MOUNTING PDC/PMA SENSOR FRT ? X nn	1	71.60	71.60
LH HEADLIGHT LED TECHNOLOGY / cut	1	2,399.10	2,399.10
Total Parts :			5,454.50

Performance Motors Limited

A Sime Darby Motors Company
 Co. Reg. No. 197401559W GST Reg. No M2-0020081-x
 Toll-Free Number (1800-2255269)



303, Alexandra Road
 Sime Darby Performance Centre
 Singapore 159941
 Fax. 64747770

280, Kampong Arang Road
 East Coast Centre
 Singapore 438180
 Fax. 63449773

315, Alexandra Road
 Sime Darby Business Centre
 Singapore 159944
 Fax. 64796601 (AfterSales)
 64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 62884 Date Estimated : 12/08/2022 Prepared By : Jack Ng Guo Ming	Page No. : 2 of 5
--	-------------------

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLR8989H	WBA12AK0207H36866	29/09/2021	218i Gran Coupe	15

Steve (LKK)
 17/10/22, 11.30am
 M R
 PIP
 by Bel by
 4 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary work must be approved and is subject to final approval from our insurance Company

Acknowledged by Repairer
 Signature:
 Date:

	Labour 1	:	5,783.00
	Parts	:	5,454.50
	Labour 2	:	0.00
	Excess	:	0.00
	Total GST @ 7%	:	786.63
	Grand Total	:	12,024.13

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**
 ** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **