



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

## Immediate Advice

To : AXA Insurance Pte Ltd

DATE: 20/10/2022

### Survey details

|                     |                   |
|---------------------|-------------------|
| Date of loss        | 10/8/2022         |
| Date of appointment | 12/8/2022         |
| Date of survey      | 22/8/2022         |
| Location of survey  | GARAGE 13 PTE LTD |

### Vehicle Details:

|                      |                     |
|----------------------|---------------------|
| Claim Type:          | THIRD PARTY         |
| Vehicle number       | GBL 7442A           |
| Make and Model       | TOYOTA HIACE MANUAL |
| Date of registration | 12/3/2017           |
| Excess               |                     |
| Market Value         | \$40,000.00         |
| Parf Rebate          | \$18,898.00         |
| Nett Loss            | \$21,102.00         |

### Repair details

|                  |  |
|------------------|--|
| Initial Estimate |  |
|------------------|--|

### Proposed/Revised repair cost:

|                          |              |
|--------------------------|--------------|
| Parts                    |              |
| "Check items (Estimated) |              |
| Labour                   |              |
| Total                    |              |
| Lump Sum (Estimated)     |              |
|                          |              |
| Number of days of repair | 4 days (est) |

### **Remarks:**

Damages Consistent.

The estimate repair cost of the damaged vehicle is in the region of \$4,000.00 to \$5,000.00