



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKP 6512K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT DOOR - LH (SN)	DENTED	1,250.00	937.50
1	FRONT DOOR WEATHER STRIP - LH (SN)	NOT NECESSARY	188.00	-
1	FRONT DOOR INNER BLACK TAPE - LH (SN)	NECESSARY	63.00	47.25
1	FRONT DOOR GLASS RUN - LH (SN)	NOT NECESSARY	113.00	-
1	FRONT DOOR HOLE COVER - LH (PLASTIC) (SN)	NOT NECESSARY	80.00	-
1	FRONT DOOR B-PILLAR TRIM (OUTSIDE) - LH (SN)	NECESSARY	325.00	243.75
1	REAR DOOR B-PILLAR TRIM (OUTSIDE) - LH (SN)	NECESSARY	450.00	337.50
1	REAR DOOR - LH (SN)	DENTED	1,250.00	937.50
1	REAR DOOR WEATHER STRIP - LH (SN)	NOT NECESSARY	200.00	-
1	REAR DOOR INNER BLACK TAPE - LH (SN)	NECESSARY	90.00	67.50
1	REAR DOOR GLASS RUN - LH (SN)	NOT NECESSARY	113.00	-
1	REAR DOOR HOLE COVER - LH (PLASTIC) (SN)	NOT NECESSARY	80.00	-
1	REAR DOOR WINDOW REGULATOR - LH (SN)	NOT NECESSARY	225.00	-
1	REAR DOOR WINDOW MOTOR - LH (SN)	NOT NECESSARY	450.00	-
1	STONE CHIP (SN)	NECESSARY	180.00	180.00
1	SUNDRIES (SN)	NOT NECESSARY	350.00	-
			5,407.00	2,751.00
	<u>LABOUR</u>			
	TO REMOVE AND TRANSFER LHS FRONT DOOR AND LHS REAR DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.		400.00	200.00
	TO DISMANTLE AND RENEW LHS FRONT DOOR AND LHS REAR DOOR. TO REPAIR LHS SILL PANEL. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.		1,500.00	700.00
	TO RESPRAY LHS FRONT DOOR, LHS REAR DOOR, LHS SILL PANEL, DOOR HANDLE, DOOR HINGES AND LHR REAR FENDER.		2,400.00	1,050.00
	TO CARRY OUT DIAGNOSTIC CHECK.		192.00	50.00
			4,492.00	2,000.00
	GRAND TOTAL		9,899.00	4,751.00

Report Ref No. CS/SMR22007695/Ecy3e2



RECOMMENDED COST OF REPAIRS			4,751.00
------------------------------------	--	--	-----------------

Report Ref No. CS/SMR22007695/Ecy3e2

CHEN TSUE YEE

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.