



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR22007695/Ecy3e2 Date: 15/03/2023 Code: SMR	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SMB 77P	Veh. Inspected	SKP 6512K	
Policy No.		Coverage (\$)	0.00	
Claim No.	BUS/08/22/5007	Excess (\$)	0.00	
Assign From	HUA YEN	Assign Date	12/08/2022	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	TOYOTA ALTIS	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	MR053REH104516003	Colour	GREY	
Odometer	151958 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	185/60 R15	MICHELIN	4 mm	
L/H Front Tyre	185/60 R15	MICHELIN	4 mm	
R/H Rear Tyre	185/60 R15	MICHELIN	4 mm	
L/H Rear Tyre	185/60 R15	MICHELIN	4 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	10/08/2022	Inspection Date	15/08/2022	
Survey held at	24 Benoi Sector			
Repairer	PREMIUM AUTOMOBILES PTE LTD			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			6 Working Days	