

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0693/2022/EQ
DATE : 15-Aug-22
WIP :

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 15/08/2022
YOUR INSURED VEH NO : SMB 77 P

STRIDES AUTOMOTIVE SERVICES Pte Ltd
60 WOODLANDS INDUSTRIAL PARK E4
SINGAPORE 757705
Attn: Motor Claims Dept
Tel: 6866 2615 - Fax: 6368 7421

OWNER'S NAME : TERASAKI ELECTRIC COMPANY (FAR EAST) PTE LTD
ADDRESS : BLK 2 HILLVIEW RISE
#11-11
SINGAPORE 667978
TELEPHONE : HP +65 96816948
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 5103299131-03
VEHICLE NO : SKP 6512 K
MODEL CODE : TOYOTA COROLLA ALTISD 1.6L
MODEL YEAR : YEAR 2014
ENGINE NO : 1ZR447266
CHASSIS NO : MR053REH104516003
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 10-Aug-22
PLACE OF ACCIDENT : BUKIT BATOK EAST AVE 2

PREMIUM AUTOMOBILES




55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKP 6512 K

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER LHS FRONT DOOR AND LHS REAR DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$ 400.00	100 200 ✓
2	TO DISMANTLE AND RENEW LHS FRONT DOOR AND LHS REAR DOOR. TO REPAIR LHS SILL PANEL. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 1,500.00	700 ✓
3	TO RESPRAY LHS FRONT DOOR, LHS REAR DOOR, LHS SILL PANEL, DOOR HANDLE, DOOR HINGES AND LHR REAR FENDER.	\$ 2,400.00	1050 ✓
5	TO CARRY OUT DIAGNOSTIC CHECK	S/N \$ 192.00	20 50 ✓
TOTAL LABOUR CHARGES		: \$ 4,492.00	

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG


MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKP 6512 K

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT DOOR - LH / DD	1	\$ 1,250.00	937.50 ✓	
2	FRONT DOOR WEATHER STRIP - LH X nn	1	\$ 188.00		
3	FRONT DOOR INNER BLACK TAPE - LH / nn	1	\$ 63.00	47.25 ✓	
4	FRONT DOOR GLASS RUN - LH X nn	1	\$ 113.00		
5	FRONT DOOR HOLE COVER - LH (PLASTIC) X nn	1	\$ 80.00		
6	FRONT DOOR B-PILLAR TRIM (OUTSIDE) - LH X ✓ nec	1	\$ 325.00	243.75 ✓	
7	REAR DOOR B-PILLAR TRIM (OUTSIDE) - LH X ✓ nec	1	\$ 450.00	337.50 ✓	
8	REAR DOOR - LH / DD	1	\$ 1,250.00	937.50 ✓	
9	REAR DOOR WEATHER STRIP - LH X nn	1	\$ 200.00		
10	REAR DOOR INNER BLACK TAPE - LH / nn	1	\$ 90.00	67.50 ✓	
11	REAR DOOR GLASS RUN - LH X nn	1	\$ 113.00		
12	REAR DOOR HOLE COVER - LH (PLASTIC) X nn	1	\$ 80.00		
13	REAR DOOR WINDOW REGULATOR - LH X nn	1	\$ 225.00		
14	REAR DOOR WINDOW MOTOR - LH X nn	1	\$ 450.00		
15	STONE CHIP / nnc	S/N	\$ 180.00	180 ✓	
16	SUNDRIES X nn		\$ 350.00		
TOTAL SPARE PARTS		:	\$ 5,407.00		
TOTAL LABOUR CHARGES		:	\$ 4,492.00		
GRAND TOTAL		:	\$ 9,899.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

- 25% Disc
Pne chuk

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

Steer (LKK)
15/8/77 11.11

W R
P/P
Lg R L y
6 Lys

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT