

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT					
	INCOME INSURANCE LTD		Ref:	CS/INC22007720/Tny3e2	
	75 BRAS BASAH ROAD INCOME CENTRESINGAPORE 189557		Date:	26/05/2023	
	ATTN: CHRYLLIS	QUAH	Code:	INC	
1.	1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SJZ 3028X	Veh. Inspected	SLK 1381T	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	MT/1183806-002	Excess (\$)	0.00	
	Assign From	DIANA TAY	Assign Date	15/08/2022	
2. Vehicle Particulars & Condition					
	Make & Model	TOYOTA PRIUS HYBRID	c.c	1797	
	Engine No.	HIDDEN	Year of Reg.	2017	
	Chassis No.	JTDKB3FU603542524	Colour	WHITE	
	Odometer	269744 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	195/65 R15	WINDFORCE	6 mm	
	L/H Front Tyre	195/65 R15	WINDFORCE	6 mm	
	R/H Rear Tyre	195/65 R15	WINDFORCE	6 mm	
	L/H Rear Tyre	195/65 R15	WINDFORCE	6 mm	
4.	4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.				
	DAMAGES SEE DETAILS.				
				§ *	
5.	General Information				
	Accident Date	10/08/2022	Inspect Date / Time	15/08/2022 ( 05:30 PM )	
	Survey held at	8 KAKI BUKIT AVENUE 4 #02-13 PREMIER @ KAKI BUKIT			
	Repairer	er AUTO MEGA MALL PTE LTD			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days				
	•				