

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : CHINA TAIPING INSURANCE (SINGAPORE) PTE
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909

TEL: 63896111 FAX: 62247175
ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 10/08/2022
TP Veh Reg No: YN7497J

Estimate No: EST2200257
Date: 12 Aug 2022

Veh Reg No: SMC2549B
Make/Model: TOYOTA VIOS E(A)
Chasis No: MR2B23F3301122733
Reg. Date: 28/06/2018
Your Ref No: YN7497J

Estimate Repair Cost to Vehicle No :SMC2549B

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
	List Price		
1	1 PC BOOT LID	784.30	
2	1 PC BOOT LID LOGO	52.20	
3	1 PC BOOTLID "VIOS" EMBLEM	45.50	
4	1 PC BOOTLID "E" EMBLEM	42.20	
5	2 PCS BOOT LID HINGE	194.60	
6	1 PC BOOT LID LAMP RH	388.60	
7	1 PC BOOT LID LAMP LH	388.60	
8	1 PC BOOT LID LOCK	360.40	
9	1 PC BOOT LID LOCK CHECKER	29.90	
10	1 PC BOOT LID RUBBER	166.40	
11	1 PC BOOTLID OPENER LOCK SENSOR	160.60	
12	2 PCS REAR NUMBER PLATE LAMP	124.40	
13	1 PC REAR NUMBER PLATE GARNISH	168.60	
14	1 PC BOOTLID TRIM	208.50	
15	1 PC REAR KEYLESS SENSOR	169.90	
16	1 PC REAR FENDER LH	894.80	
17	1 PC REAR FENDER TRIM LH	355.90	
18	1 PC REAR FENDER MUDFLAP LH	56.90	
19	1 PC REAR FENDER AIR DUCT COVER LH	76.40	
20	1 PC REAR FENDER TRIM RH	355.90	
21	1 PC TAIL LAMP LH	397.70	
22	1 PC TAIL LAMP PANEL LH	143.70	
23	1 PC TAIL LAMP - RH	397.70	
24	1 PC SPARE TYRE COVER	206.90	
25	1 PC SPARE TYRE PANEL LH SPONGE	167.70	
26	1 PC SPARE TYRE PANEL RH SPONGE	167.70	
27	1 PC REAR SPARE TYRE PANEL LH SIDE PANEL	114.60	
28	1 PC REAR PANEL	620.10	
29	1 PC REAR PANEL TRIM	232.20	

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : CHINA TAIPING INSURANCE (SINGAPORE) PTE
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909

TEL: 63896111 FAX: 62247175
ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 10/08/2022
TP Veh Reg No: YN7497J

Estimate No: EST2200257
Date: 12 Aug 2022

Veh Reg No: SMC2549B
Make/Model: TOYOTA VIOS E(A)
Chasis No: MR2B23F3301122733
Reg. Date: 28/06/2018
Your Ref No: YN7497J

Estimate Repair Cost to Vehicle No :SMC2549B

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
30	1 PC REAR BUMPER	452.60	
31	1 PC REAR BUMPER REINFORCEMENT	316.60	
32	2 PCS REAR BUMPER SIDE RETAINER	263.80	
33	2 PCS REAR BUMPER SMALL RETAINER	181.20	
34	1 PC REAR BUMPER REFLECTOR - LH	98.70	
		8,785.80	
	Less 25%	2,196.45	6,589.43
	Special Net		
35	1 PC BOOT LID NUMBER '614' STICKER	50.00	
36	1 PC REAR NUMBER PLATE	50.00	
37	1 SET REAR FENDER TRIM CLIPS LH	60.00	
38	1 SET REAR FENDER MUDFLAP CLIPS LH	30.00	
39	1 SET REAR FENDER TRIM CLIPS RH	60.00	
40	1 SET REAR PANEL TRIM CLIPS	40.00	
41	2 PCS "L" PLATE BRACKET	100.00	
42	1 SET REAR BUMPER STICKER	280.00	
43	1 SET REAR BUMPER CLIPS	60.00	
44	1 PC REAR WINDSCREEN SEAL	60.00	
45	1 PC REAR WINDSCREEN INNER SEAL RUBBER	60.00	
46	1 SET BOOTLID TRIM CLIPS	60.00	
		910.00	910.00
	Labour		
47	1 TO CHECK WIRING	50.00	
48	1 TO REMOVE AND REFIT REAR WINDSCREEN	120.00	
49	1 TO REMOVE AND REFIT SEAT CUSHION & TRIM	200.00	
50	1 TO REPLACE STICKERS	80.00	
51	1 TO SPRAY PANEL SEALANT	150.00	
52	1 (REAR) TO SPRAY PAINTING	1,500.00	

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : CHINA TAIPING INSURANCE (SINGAPORE) PTE
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909

TEL: 63896111 FAX: 62247175
ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 10/08/2022
TP Veh Reg No: YN7497J

Estimate No: EST2200257
Date: 12 Aug 2022

Veh Reg No: SMC2549B
Make/Model: TOYOTA VIOS E(A)
Chasis No: MR2B23F3301122733
Reg. Date: 28/06/2018
Your Ref No: YN7497J

Estimate Repair Cost to Vehicle No :SMC2549B

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
53	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	2,000.00	
		4,100.00	4,100.00
		Total	S\$ 11,599.43
		Add GST @ 7%	811.96
		Total Amount Payable	<u>S\$ 12,411.39</u>

TOTAL: SINGAPORE DOLLAR TWELVE THOUSAND FOUR HUNDRED ELEVEN AND CENTS THIRTY NINE ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

For Kang Car Repairers Pte Ltd



AUTHORISED SIGNATURE