



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD

75 BRAS BASAH ROAD
INCOME CENTRESINGAPORE 189557

ATTN: CHARLOTTE CHEW

Ref: CS/INC22007739/Tvy3m4

Date: 24/04/2023

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLU 1088M	Veh. Inspected	FBA 4339T
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1183100-002	Excess (\$)	0.00
Assign From	DIANA TAY	Assign Date	15/08/2022

2. Vehicle Particulars & Condition

Make & Model	HONDA CB400	c.c	399
Engine No.	HIDDEN	Year of Reg.	2006
Chassis No.	JH2NC39915M100258	Colour	BLUE
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	120/70 R17	BRIDGESTONE	5 mm
L/H Front Tyre			mm
R/H Rear Tyre	120/70 R17	BRIDGESTONE	5 mm
L/H Rear Tyre			mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S AND N/S BODY.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	04/08/2022	Inspect Date / Time	15/08/2022 (04:00 PM)
Survey held at	SYNERGY @ KAKI BUKIT 23, #01-18 KAKI BUKIT RD 4		
Repairer	ERZAT LEE MOTOR TRADING PTE LTD		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **3 Working Days**