

SM AUTOMOTIVE

N TUC

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883

Blk 1 Kaki Bukit Ave 6

Email: SM_AUTOMOTIVE@HOTMAIL.COM

11/8/2022

01-43

Tel: (65) 6747 9241

Fax: (65) 6741 7276

Singapore 417883

RCB No: 53231488C

GST Reg No : 53231488C

Accident date: 11/08/2022

TP INC
online

Estimated repair cost for vehicle no: SLB9192S KIA FORTE K3 1.6A SX

CHASSIS: KNAFZ411MG5601047 (2016)

S/n	Qty	Items	U/price	Amount	
1	1	REAR BOOTLID <i>Dented</i>	\$1,397.00	<u>\$1,397.00</u>	✓ 1072
2	1	REAR BOOTLID LOCK <i>2nd</i>	\$169.00	\$169.00	✓
3	1	REAR BOOTLID LOCK CATCH <i>new</i>	\$17.00	\$17.00	+
4	1	REAR BOOTLID INNER TRIM <i>new</i>	\$92.00	\$92.00	+
5	2	REAR BOOTLID LAMP <i>cut</i>	\$772.00	<u>\$1,544.00</u>	✓ 1392
6	1	REAR BOOTLID LOCK DETECTOR <i>new</i>	\$198.00	\$198.00	+
7	2	REAR BOOTLID NUMBER PLATE LAMP <i>new</i>	\$18.00	\$36.00	+
8	1	REAR BOOTLID TOP SPOILER <i>new</i>	\$590.00	\$590.00	+
9	1	REAR BOOTLID LOGO <i>2</i>	\$32.00	\$32.00	✓
10	1	REAR BOOTLID EMBLEM FORTE <i>new</i>	\$26.00	\$26.00	✓
11	1	REAR BOOTLID EMBLEM K3 <i>1</i>	\$24.00	\$24.00	✓
12	1	REAR BUMPER <i>Distorted</i>	\$602.00	\$602.00	✓
13	1	REAR BUMPER LOWER DIFFUSER <i>Dented</i>	\$234.00	\$234.00	✓
14	1	REAR BUMPER REINFORCEMENT <i>Distorted</i>	\$304.00	\$304.00	✓
15	2	REAR BUMPER REINFORCEMENT BRACKET <i>Dented</i>	\$75.00	\$150.00	✓
16	2	REAR BUMPER SIDE RETAINER <i>new</i>	\$19.00	\$38.00	✓
17	5	REAR BUMPER BRACKET <i>2nd</i>	\$12.00	\$60.00	✓
18	2	REAR BUMPER REFLECTOR <i>crushed</i>	\$99.00	\$198.00	✓
19	4	REAR BUMPER REVERSE SENSOR <i>3 pieces damaged</i>	\$172.00	\$688.00	✓ 346
20	4	REAR BUMPER REVERSE SENSOR BRACKET <i>new</i>	\$18.00	\$72.00	✓
21	1	REAR BUMPER REVERSE SENSOR WIRE HARNESS <i>new</i>	\$273.00	\$273.00	+
22	2	REAR BUMPER SIDE GUIDE <i>new</i>	\$62.00	\$124.00	+
23	1	REAR WEATHER STRIPE <i>cut</i>	\$82.00	\$82.00	✓
24	1	REAR END PANEL <i>Distorted</i>	\$315.00	\$315.00	✓
25	1	REAR END PANEL TOP AGRNISH <i>Dented</i>	\$58.00	\$58.00	✓
26	1	REAR KEYLESS SENSOR <i>3rd</i>	\$87.00	\$87.00	+
27	1	REAR KEYLESS SENSOR BUZZER <i>new</i>	\$48.00	\$48.00	+
28	2	REAR TAILLAMP <i>crushed</i>	\$858.00	<u>\$1,716.00</u>	✓ 1584
29	2	REAR TAILLAMP LOWER BRACKET <i>new</i>	\$36.00	\$72.00	+
30	2	REAR TAILLAMP INNER PANEL <i>Repair</i>	\$126.00	\$252.00	+
31	2	REAR FENDER INNER TRIM <i>LH torn</i>	\$156.00	<u>\$312.00</u>	✓ 156

SLB9192S KIA FORTE K3 1.6A SX

32	1	REAR SPARE TYRE COMPARTMENT PANEL	Buckled	\$712.00	\$712.00	✓
33	1	REAR SPARE TYER PANEL TOP BOARD	torn	\$165.00	\$165.00	✓
34	1	REAR EXHUAUST MUFFLER	new	\$812.00	\$812.00	+
35	2	REAR EXHUAUST MUFFLER RUBBER MOUNTING	new	\$26.00	\$52.00	+
36	1	REAR EXHUAUST MUFFLER CHROME	cut	\$36.00	\$36.00	✓
37	1	Reas Exhaust Heat Shield	125 ✓ crimped			
38	1	Reas Bumper Side Undercovers	76 75. ✓ torn			
				TOTAL :	\$11,587.00	
				LESS 10 %	\$1,158.70	
				SUB-TOTAL :	\$10,428.30	

S/N	Qty	ITEMS / SPECIAL NETT	U/price	Amount
1	1	REAR BUMPER CLIPS <i>New</i>	\$80.00	\$80.00 <i>30</i>
2	1	REAR BOOTLID INNER TRIM CLIPS <i>New</i>	\$60.00	\$60.00 <i>1</i>
3	2	REAR FENDER INNER TRIM CLIPS <i>new</i>	\$40.00	\$40.00 <i>20</i>
4	1	REAR NUMBER PLATE WITH CASING <i>Best</i>	\$60.00	\$60.00 <i>✓</i>
5	1	REAR END PANEL SEALANT <i>New</i>	\$120.00	\$120.00 <i>60</i>
6	1	REAR SPARE TYER PANEL SEALANT <i>new</i>	\$150.00	\$150.00 <i>60</i>
7	1	REAR BOOTLID CAMERA <i>Damnd</i>	\$480.00	\$480.00 <i>380</i>
8	1	<i>Reas Spare Tyre Panel Insulation Pad</i> <i>280 200</i> NEC		
			TOTAL:	\$990.00
			TOTAL PARTS :	\$11,418.30

Labour charges

1	LABOUR FOR PANEL BEATING	\$1,600.00	1200
2	LABOUR FOR SPRAYPAINTING	\$1,500.00	1800
3	TO APPLY TUFF COATING/RUST PROOF ACCIDENT AREAS	\$300.00	100
4	WIRING CHECK	\$80.00	30
5	LABOUR FOR REMOVE & RENEW REAR EXHUAUST MUFFLER ,TO REPAIR & STRAIGHTEN REAR EXHUAUST PIPE	\$300.00	80
6	LABOUR FOR REMOVE & REFIX REAR UPHOSTERY / CARPET	\$300.00	100
7	LABOUR FOR REMOVE & TRANSFER ALL REAR BOOTLID FITTING	\$200.00	60

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Subtotal :- \$4,280.00

Total:- \$15,698.30

Total: 10757.30

h/s: 8.6K

Admin
h/s 15/08/22
09 Days

09 Days
8.6K