



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924		Ref: CS/AGI22007755/Kvy3q2 Date: 30/08/2022	Code: AGI
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SMJ 2713G	Veh. Inspected	SLJ 7939B
Policy No.	P10510275R01	Coverage (\$)	0.00
Claim No.	C10016881/JT	Excess (\$)	0.00
Assign From	MAYBIE CHUA	Assign Date	15/08/2022
2. Vehicle Particulars & Condition			
Make & Model	MAZDA 2 (A)	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	MM6DL2SAAGW196539	Colour	METALLIC BLUE
Odometer	54513 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	185/60 R16	DUNLOP	3 mm
L/H Front Tyre	185/60 R16	DUNLOP	3 mm
R/H Rear Tyre	185/60 R16	DUNLOP	2 mm
L/H Rear Tyre	185/60 R16	DUNLOP	2 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	11/08/2022	Inspection Date	16/08/2022
Survey held at	ACCORD AUTO SERVICES PTE LTD 10 ANG MO KIO INDUSTRIAL PARK 2A AMK AUTO POINT #03-11 SINGAPORE 568047		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	