

ASS. FEQ. BY:

REP:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rport: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SJQ26T Yr Regn: 2018, Oct.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Lexus RX 300 c.c. 1998

Colour: White A/C: Insured / Std / NI / NA

Sp.Reading: 125304 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTJZAMCA302048609.

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modif: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 235/55 R18.

R: 235/55 R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. _____ D.O.I. 15/08/22.

Survey held at N51.

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front N/S.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>OD Chiam.</u>
	<u>MV: 182K</u>
	<u>PV: 68K</u>
	<u>Nett: 114K</u>

Date/Time, File Pass to?

: Prel. Report

1)

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

Add Fee:

Site Insp (\$)

Interview (\$)

Tech. Insp (\$)

_____ + 1/5 _____ \$

_____ \$

Others

Report Format: _____

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 12/08/2022 17:03 (SGT)
Reported by Both
Date of Accident 11/08/2022 22:30 (SGT)
Exact Location of Accident Singapore
Additional Location Information YIO CHU KANG SLIP RD INTO SLE(BKE)
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SJQ26T

INSURED/POLICYHOLDER

Is company? No
Name Of Registered Owner LIM HOCK SENG
NRIC No S1238777F
Email Address hs.lim551@gmail.com
Mobile Phone No (Phone) +65-96669980
Alternative Phone No -

VEHICLE PARTICULARS

Manufacturer Lexus
Model Nx300
Variant -
Exact purpose for which vehicle was being used at time of accident Private use
Are you claiming under your own insurance policy for repair to your vehicle? Yes
Vehicle Category Private car
Transmission Auto
CC 1998

INSURANCE COMPANY

Name of Insurance Company China Taiping Insurance (Singapore) Pte. Ltd.
Policy Number / Cover Note Number DMPCSNW00202242101

DRIVER

Name of Driver LIM HOCK SENG
NRIC No S1238777F
Date Of Birth 13/10/1957
Occupation Outdoor

Date Of Driving Pass	22/11/1976
Driving experience	45 YEARS AND 9 MONTHS
Gender	Male
Mobile Number	(Phone) +65-96669980
Alt. Phone Number	-
Email Address	hs.lim551@gmail.com
Address	BLK 583 WOODLANDS DR 16
Address complement	#07-464
Postcode	730583
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Hit by fallen tree / Other objects
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	1
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	No
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

PLS REFER TO THE ATTACHED STATEMENT.

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Traffic Police Department for investigation.
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


 - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
 (collectively the "Purposes")
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

[Signature] 12/08/22
 Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time


[Signature] 12/08/22
 Witnessed by Reporting Centre Personnel (Name as in NRIC/ID card)

Sketch Plan




Describe Circumstance of the Accident

On the above date & time, I was driving my vehicle SJR 26T along the
 on my way back home after an meeting at Debra Lane with my
 designer. As I was driving at a moderate speed, suddenly I
 felt my front wheel went over something on the road surface.
 At that junction, my vehicle lost control, veered to the left,
 mounted the left side road kerb and curved into a tree. After
 the accident, I managed to drive down from the left side road kerb
 and stopped by the side of the road. I alighted from my vehicle
 and made a check. I noticed that there wasn't any other government
 property was damaged except the tree. The front portion of my vehicle was
 badly damaged. I also noticed the the left rear door lower portion
 was also damaged and rear left wheel was also got grooved marks. I suspected
 that when my vehicle went over something that was on the road, it flew
 out and hit onto the rear left door area. I called for towing
 and took my vehicle to my workshop.




Declaration
 I/We declare the foregoing particulars are true in every respect.


 Policyholder's Signature / Date & Time

12/08/22

Driver's Signature (if driver is not the policyholder) / Date
 & Title

 12/08/22
 Witnessed by Reporting Centre Personnel
 (Name as in NRCCID card)

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

LIM HOCK SENG
 BLK 583 WOODLANDS DRIVE 16 #07-464
 SINGAPORE 730583

Contact : 96669980

TAX INVOICE

Repair Code : CLM17327

Date in : 12/08/2022

Vehicle Num. : SJQ26T

Model : TOYOTA LEXUS RX300 5DR SUV (AT) (2WD) EXECUTIVE

Chassis/Eng# : JTJZAMCA302048609/8ARW936420

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
ENGINE LH SIDE UNDER COVER <i>32ch d</i>	1	120.00	✓ 120.00
ENGINE LH UNDER COVER	1	180.00	✓ 180.00
FRONT BONNET <i>Dented.</i>	1	1200.00	✓ 1,200.00
FRONT BONNET DAMPER L/R <i>He m</i>	2	160.00	+ 320.00
FRONT BONNET HINGES L/R <i>Bent.</i>	2	55.00	✓ 110.00
FRONT BONNET INSULATOR MAT <i>3 Noe Nee</i>	1	260.00	+ 260.00
FRONT BONNET INSULATOR MAT CLIPS	8	3.00	+ 24.00
FRONT BONNET RUBBER SEAL <i>new</i>	1	55.00	✓ 55.00
FRONT BUMPER <i>Distorted</i>	1	420.00	✓ 420.00
FRONT BUMPER INNER SPONGE <i>crushed</i>	1	95.00	✓ 95.00
FRONT BUMPER LH FOGLAMP <i>missing</i>	1	330.00	✓ 330.00
FRONT BUMPER LH FOGLAMP COVER	1	120.00	✓ 120.00
FRONT BUMPER LH FOGLAMP COVER CHROME MOULDING <i>missing</i>	1	280.00	✓ 280.00
FRONT BUMPER LH INNER AIR GUIDE (LOWER) ?	1	90.00	? 90.00
FRONT BUMPER LH INNER AIR GUIDE (TOP) ?	1	90.00	? 90.00
FRONT BUMPER LH SIDE COVER <i>Distorted.</i>	1	60.00	✓ 60.00
FRONT BUMPER LH SIDE LOWER LID GARNISH <i>Distorted</i>	1	250.00	✓ 250.00
FRONT BUMPER LOWER CENTER LID GARNISH	1	180.00	✓ 180.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHrb
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

LIM HOCK SENG
 BLK 583 WOODLANDS DRIVE 16 #07-464
 SINGAPORE 730583

Contact : 96669980

TAX INVOICE

Repair Code : CLM17327

Date in : 12/08/2022

Vehicle Num. : SJQ26T

Model : TOYOTA LEXUS RX300 5DR SUV (AT) (2WD) EXECUTIVE

Chassis/Eng# : JTJZAMCA302048609/8ARW936420

Description	QTY	Unit Price	Total Price	Remarks
FRONT BUMPER LOWER GRILLE ?	1	320.00	320.00	?
FRONT BUMPER LOWER GRILLE CHROME MOULDING ?	1	330.00	330.00	?
FRONT BUMPER LOWER GRILLE LH COVER ?	1	35.00	35.00	?
FRONT BUMPER LOWER UNDER COVER ?	1	200.00	200.00	?
FRONT BUMPER PARKING SENSOR <i>1 piece missing</i>	2	210.00	420.00	210
FRONT BUMPER PARKING SENSOR 'O' RING <i>new</i>	2	28.00	56.00	✓
FRONT BUMPER PARKING SENSOR HOLDER BRACKET <i>new</i>	4	28.00	112.00	✓
FRONT BUMPER PARKING SENSOR WIRE HARNESS <i>new</i>	1	380.00	380.00	x
FRONT BUMPER REINFORCEMENT <i>new</i>	1	270.00	270.00	x
FRONT BUMPER SIDE RETAINER L/R <i>lit by d</i>	2	58.00	116.00	58
FRONT ENGINE CROSS MEMBER <i>new</i>	1	1600.00	1,600.00	x
FRONT ENGINE CROSS MEMBER BRACKET LH (FRONT) ?	1	160.00	160.00	?
FRONT ENGINE CROSS MEMBER BRACKET LH (REAR) ?	1	160.00	160.00	?
FRONT ENGINE CROSS MEMBER MOUNTING (FRONT) <i>new</i>	2	100.00	200.00	x
FRONT ENGINE CROSS MEMBER MOUNTING (REAR) <i>new</i>	2	100.00	200.00	x
FRONT GRILLE ?	1	760.00	760.00	?
FRONT GRILLE 'LOGO' EMBLEM ?	1	180.00	180.00	?
FRONT GRILLE CHROME MOULDING ?	1	370.00	370.00	?

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

LIM HOCK SENG
 BLK 583 WOOLANDS DRIVE 16 #07-464
 SINGAPORE 730583

Contact : 96669980

TAX INVOICE

Repair Code : CLM17327

Date in : 12/08/2022

Vehicle Num. : SJQ26T

Model : TOYOTA LEXUS RX300 5DR SUV (AT) (2WD) EXECUTIVE

Chassis/Eng# : JTJZAMCA302048609/8ARW936420

DESCRIPTION	QTY	UNIT PRICE	TOTAL PRICE	REMARKS
FRONT GRILLE UPPER RUBBER SEAL <i>Neu</i>	1	78.00	78.00	X
FRONT GRILLE UPPER TOP COVER <i>Not Me</i>	1	175.00	175.00	X
FRONT HEADLAMP L/R <i>LH cracked</i>	2	1550.00	3100.00	1550 3,100.00
FRONT HEADLAMP PANEL <i>Distorted</i>	1	650.00	650.00	✓
FRONT LH ABS SENSOR <i>Neu</i>	1	210.00	210.00	X
FRONT LH AUTO COOLER <i>Distorted</i>	1	450.00	450.00	✓
FRONT LH AUTO COOLER AIR DUCT <i>Distorted</i>	1	180.00	180.00	✓
FRONT LH AUTO COOLER BRACKET <i>Best</i>	1	200.00	200.00	✓
FRONT LH CONVERTER UNIT <i>Neu</i>	1	850.00	850.00	X
FRONT LH DOOR <i>Repis</i>	1	560.00	560.00	X
FRONT LH DOOR FRAME STICKER (NO:1)	1	60.00	60.00	X
FRONT LH DOOR FRAME STICKER (NO:2)	1	60.00	60.00	X
FRONT LH DOOR FRAME STICKER (NO:3)	1	60.00	60.00	X
FRONT LH DOOR PROTECTOR GARNISH	1	200.00	200.00	X
FRONT LH DOOR UPPER MOULDING RIVET	8	3.00	24.00	X
FRONT LH DOOR VERTICAL GARNISH	1	120.00	120.00	X
FRONT LH DOOR WEATHER STRIP SEAL	1	105.00	105.00	X
FRONT LH DRIVE SHAFT <i>?</i>	1	820.00	820.00	X

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n5 .com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

LIM HOCK SENG
 BLK 583 WOODLANDS DRIVE 16 #07-464
 SINGAPORE 730583

Contact : 96669980

TAX INVOICE

Repair Code : CLM17327

Date in : 12/08/2022

Vehicle Num. : SJQ26T

Model : TOYOTA LEXUS RX300 5DR SUV (AT) (2WD) EXECUTIVE

Chassis/Eng# : JTJZAMCA302048609/8ARW936420

FRONT LH FENDER	<i>Distorted</i>	1	440.00	✓	440.00
FRONT LH FENDER ARCH GARNISH	<i>Missing</i>	1	185.00	✓	185.00
FRONT LH FENDER INNER COVER	<i>?</i>	1	75.00	?	75.00
FRONT LH FENDER INNER PANEL	<i>?</i>	1	370.00	?	370.00
FRONT LH FENDER INNER PANEL TOP COVER	<i>del'd</i>	1	180.00	✓	180.00
FRONT LH FENDER INNER SHIELD	<i>lon.</i>	1	200.00	✓	200.00
FRONT LH FENDER QUARTER GARNISH	<i>new</i>	1	75.00	+	75.00
FRONT LH FENDER SIDE BRACKET	<i>Best.</i>	1	65.00	✓	65.00
FRONT LH FENDER WHEEL HOUSE	<i>?</i>	1	420.00	?	420.00
FRONT LH FUSE BOX CASING	<i>ht</i>	1	380.00	✓	380.00
FRONT LH FUSE BOX TRAY	<i>?</i>	1	200.00	?	200.00
FRONT LH FUSE BOX WIRE HARNESS ASSY	<i>new</i>	1	2900.00	+	2,900.00
FRONT LH HEADLAMP CONTROL UNIT	<i>?</i>	1	480.00	?	480.00
FRONT LH KNUCKLE ARM	<i>?</i>	1	350.00	?	350.00
FRONT LH KNUCKLE ARM BEARING	<i>?</i>	1	110.00	?	110.00
FRONT LH LINKAGE	<i>?</i>	1	80.00	?	80.00
FRONT LH LOWER ARM	<i>?</i>	1	240.00	?	240.00
FRONT LH LOWER ARM BALL JOINT	<i>?</i>	1	125.00	?	125.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

LIM HOCK SENG
 BLK 583 WOODLANDS DRIVE 16 #07-464
 SINGAPORE 730583

Contact : 96669980

TAX INVOICE

Repair Code : CLM17327
 Date in : 12/08/2022
 Vehicle Num. : SJQ26T
 Model : TOYOTA LEXUS RX300 5DR SUV (AT) (2WD) EXECUTIVE
 Chassis/Eng# : JTJZAMCA302048609/8ARW936420

FRONT LH SHOCK ABSORBER	1	300.00	?	300.00
FRONT LH SHOCK ABSORBER MOUNTING	1	100.00	+	100.00
FRONT LH SHOCK ABSORBER MOUNTING BEARING	1	80.00	+	80.00
FRONT LH SHOCK ABSORBER MOUNTING RUBBER	1	60.00	+	60.00
FRONT LH SHOCK ABSORBER MOUNTING SPONGE	1	70.00	+	70.00
FRONT LH SPORT RIM <i>lt.</i>	1	2500.00	<i>two</i>	2500.00
FRONT LH STEERING TIE ROD END	1	105.00	?	105.00
FRONT LH WHEEL HUB	1	330.00	?	330.00
FRONT LH WIPER BLADE <i>new</i>	1	85.00	x	85.00
FRONT STABILIZER BAR <i>new</i>	1	320.00	+	320.00
FRONT STEERING RACK & PINION	1	1800.00	?	1,800.00
FRONT WINDSCREEN GLASS <i>cracked</i>	1	1050.00	✓	1,050.00
FRONT WINDSCREEN GLASS SEAL <i>new</i>	1	75.00	✓	75.00
FRONT WINDSCREEN GLASS SIDE MOULDING L/R <i>new</i>	2	85.00	✓	170.00
FRONT WIPER GRILLE GARNISH <i>lt.</i>	1	290.00	✓	290.00
REAR LH DOOR <i>Deited.</i>	1	750.00	✓	750.00
REAR LH DOOR ARCH GARNISH <i>new</i>	1	95.00	x	95.00
REAR LH DOOR ARCH RUBBER SEAL <i>new</i>	1	105.00	x	105.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

LIM HOCK SENG
 BLK 583 WOODLANDS DRIVE 16 #07-464
 SINGAPORE 730583

Contact : 96669980

TAX INVOICE

Repair Code : CLM17327

Date in : 12/08/2022

Vehicle Num. : SJQ26T

Model : TOYOTA LEXUS RX300 5DR SUV (AT) (2WD) EXECUTIVE

Chassis/Eng# : JTJZAMCA302048609/8ARW936420

REAR LH DOOR FRAME STICKER (NO:1)	1	57.00	✓	57.00
REAR LH DOOR FRAME STICKER (NO:2)	1	57.00	✓	57.00
REAR LH DOOR FRAME STICKER (NO:3)	1	57.00	✓	57.00
REAR LH DOOR INNER TRIM BOARD	1	900.00	+	900.00
REAR LH DOOR PROTECTOR GARNISH	1	220.00	✓	220.00
REAR LH DOOR UPPER MOULDING RIVET	7	3.00	?	21.00
REAR LH DOOR VERTICAL GARNISH	1	120.00	x	120.00
REAR LH DOOR WEATHER STRIP	1	110.00	x	110.00
REAR LH SPORT RIM	1	2500.00	no	2,500.00
REAR LH WHEEL BEARING	1	360.00	x	360.00
Subtotal before discount				37,517.00
Percentage discount 0%				0.00
Sub-total 1				37,517.00
AUTO OIL	1	200.00	80	200.00
BATTERY ASSY	1	250.00	x	250.00
FRONT GRILLE UPPER TOP COVER CLIPS - SET	1	50.00	x	50.00
FRONT LH DOOR PROTECTOR GARNISH CLIPS - SET	1	50.00	x	50.00
FRONT LH FENDER ARCH GARNISH CLIPS - SET	1	40.00	20	40.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

LIM HOCK SENG
 BLK 583 WOODLANDS DRIVE 16 #07-464
 SINGAPORE 730583

Contact : 96669980

TAX INVOICE

Repair Code : CLM17327
 Date in : 12/08/2022
 Vehicle Num. : SJQ26T
 Model : TOYOTA LEXUS RX300 5DR SUV (AT) (2WD) EXECUTIVE
 Chassis/Eng# : JTJZAMCA302048609/8ARW936420

FRONT LH FENDER INNER SHIELD CLIPS - SET	<i>me</i>	1	50.00	<i>30</i>	50.00
FRONT LH TYRE	<i>lt</i>	1	350.00	<i>250.</i>	350.00
FRONT WINDSCREEN GLASS E.R.P BRACKET		1	25.00	<i>✓</i>	25.00
FRONT WINDSCREEN GLASS E.R.P BRACKET STICKER	<i>you</i>	1	15.00	<i>✓</i>	15.00
FRONT WINDSCREEN GLASS SEALANT	<i>me</i>	1	80.00	<i>60.</i>	80.00
REAR LH DOOR ARCH GARNISH CLIPS - SET	<i>me</i>	1	20.00	<i>✓</i>	20.00
REAR LH DOOR INNER TRIM BOARD CLIPS - SET	<i>me</i>	1	50.00	<i>+</i>	50.00
REAR LH DOOR PROTECTOR GARNISH CLIPS - SET	<i>me</i>	1	50.00	<i>30</i>	50.00
REAR LH TYRE	<i>the me</i>	1	350.00	<i>X</i>	350.00
			Subtotal before discount		1,580.00
Percentage discount 0%					0.00
			Sub-total 2		1,580.00
			Parts-total		39,097.00

LABOUR

To remove, reinstall air con parts, vacuums, refill air con gas. (to FR)	<i>?</i>	150.00
To reset system after repair works	<i>180.</i>	280.00
To remove, reinstall electrical wiring harness, check lighting, resetting headlamp focussing and rewire for parking sensor.	<i>100.</i>	400.00
To remove, change windscreen.	<i>120.</i>	150.00
To remove, install engine with transmission. (to FR)	<i>?</i>	400.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

LIM HOCK SENG
 BLK 583 WOODLANDS DRIVE 16 #07-464
 SINGAPORE 730583

Contact : 96669980

TAX INVOICE

Repair Code : CLM17327
 Date in : 12/08/2022
 Vehicle Num. : SJQ26T
 Model : TOYOTA LEXUS RX300 5DR SUV (AT) (2WD) EXECUTIVE
 Chassis/Eng# : JTJZAMCA302048609/8ARW936420

To remove, change front suspension parts, absorber, lower arm, knuckle arm, wheel bearing, bearing hub, drive shaft, anti-roll bar, top-arm and steering rack and pinion.	?	400.00
To remove, reinst. ll rear suspension and undercarriage part. (to FR)	X	150.00
To road test driving, check and resetting wheel alignments system.	80	100.00
To transfer door glass, regulator gear, motor, railing, channel, trim board, mechanism lock and handle.	80	160.00
To remove, reinstall dashboard fascia, meter reading and etc. (to FR)	X	280.00
To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	1000	1,800.00
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	1000	2,000.00
Labour Total		6,270.00
Parts & Labour Total		45,367.00

*** This is a computer-generated document which requires no signature.***
 page 8

*Adrian G
 #/s Mr Andrew
 15/08/22
 Excom \$750.*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 777F

Vehicle Details

Vehicle No.: SJQ26T
Vehicle to be Exported: No
Intended Deregistration Date: 16 Aug 2022
Vehicle Make: TOYOTA
Vehicle Model: LEXUS RX300 5DR SUV (AT) (2WD) EXECUTIVE
Primary Colour: White
Manufacturing Year: 2018
Engine No.: 8ARW936420
Chassis No.: JTJZAMCA302048609
Maximum Power Output: 175.0 kW (234 bhp)
Open Market Value: \$51,254.00
Original Registration Date: 17 Oct 2018
First Registration Date: 17 Oct 2018
Transfer Count: 1
Actual ARF Paid: \$64,258.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 16 Oct 2028
PARF Rebate Amount: \$48,193.00

Intended COE Rebate Details

COE Expiry Date: 16 Oct 2028
COE Category: B - Car above 1600cc or 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$32,001.00
COE Rebate Amount: \$19,733.00
Total Rebate Amount: \$67,926.00

The information contained herein is correct as at 16 Aug 2022

OK

HOTTEST NEW CAR PROMOTIONS



Toyota Alphard
The ultimate family car! Supreme road presence with space for the whole family and much more.

DON'T MISS OUT!

Post an Advertisement
Sell it yourself! Advertise it at just **\$68 until it's SOLD!**

1 Owner Low Maintenance 16KM/L Family Size SUV



1 and Only Highest Spec in the Market! Value for Money! Drives like Brand New!
Mace Auto Pte Ltd StarAd

Lake View Credit Pte Ltd view our cars

- > Low prices guaranteed
- > Specialist in Japanese cars
- > Easy loan approval
- > All terms are negotiable

Post an Ad Advertiser Login Ways of Selling

Sort by 20 results/page

4 vehicles



rx300

Any Category

Advanced Search



Search

Search Selection

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
rx300		Any	Any	2018	Any	Any	Any	Available
	Lexus RX300 Luxury	\$182,800	\$23,620 /yr	22-Oct-2018	1,998 cc	89,399 km	SUV	Available
<p>Latest arrival! Luxury Model! Buy with confidence with agent service history,, and valid warranty till Oct' 2023, 1 careful owner! Original paintwork. Do not miss! Call for viewing and test drive today.</p> <p>Horizon Motoring Posted: 10-Aug-2022</p>								
	Lexus RX300 Executive	\$165,777	\$21,530 /yr	30-Oct-2018	1,998 cc	-	SUV	Available
<p>An exceptional SUV in every sense, this commanding drive is all luxury and comfort. Impressive performance at 234bhp, awesome condition well loved by sole owner, fully maintained by agent. 100% loan available, call for a no obligation test drive and viewing today!</p> <p>Posted: 15-Aug-2022</p>								
	Lexus RX300 Luxur'	\$197,800	\$25,850 /yr	08-Nov-2018	1,998 cc	30,000 km	SUV	Available
<p>Very Low Mileage. Fully Service By Agent With Records. Under 5 Years Agent Warranty! And 5 Years Free Servicing!100% Accident-Free, Flawless Condition. High Loan Available And Trade-Ins Are Welcomed. Guarantee Best Condition In The Market. Call To Make Appointme...</p> <p>Posted: 18-Jul-2022</p>								
	Lexus RX300 Luxury	\$189,800	\$24,500 /yr	14-Nov-2018	1,998 cc	69,000 km	Sedan	Available
<p>1 Owner In Pristine Condition Fully Agent Maintained With Records, 5 Years Agent Warranty. Unmistakable Reliability And Drive Of The Lexus, And The RX300 Brings Out The Ultimate Comforts Of A SUV! Come On Down Today To The VINCAR Pre Owned Showroom Today...</p> <p>VINCAR Pte Ltd Posted: 26-Jun-2022</p>								

Save this search criteria, to get email alerts whenever a match is found.

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
------	-------	-------	--------------	----------	---------	---------	----------	--------

20 results/page

For old advertisements, view **Expired ads**

Buy / Rent Cars	Sell Your Car	Aftermarket	Articles	General
New Cars For Sale	Post an Ad	Workshop Directory	Car Reviews	About Us
Used Cars For Sale	Sell by Bidding	Aftermarket Products	Car Advice	Contact Us
Cars For Rent	Sell by Consignment		Car News	Careers
			Car Features	Site Map

Compare