

MFORTDELGRO ENGINEERING PTE LTD

PAIR ESTIMATE*

VEHICLE NO SHD7299T
 MAKE/REG 04.12.2018
 MODEL : HYUNDAI IONIQ G2

DATE 11.08.2022

CHIANG/NTUC

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	REAR BUMPER			\$459.40 <i>By</i>
1	REAR BUMPER BRACKET RH			\$55.80 <i>By</i>
1	REAR DOOR MOULDING RH			\$110.10 <i>By</i>
1	REAR DOOR PANEL RH			\$2,147.90 <i>By</i>
1	FRONT DOOR PANEL RH			\$2,147.90 <i>By</i>
1	FRONT DOOR MOULDING RH			\$125.30 <i>By</i>
	SUB TOTAL		235.40	\$5,046.40
	LESS 20%			\$1,009.28
	DISCOUNTED TOTAL		188.32	\$4,037.12
1	FRONT DOOR COMFORT STICKER		<i>12.5 10% cut</i>	\$75.00
1	REAR DOOR COMFORT APP		<i>10% cut</i>	\$80.00
			139.50	\$139.50
	Labour Charge			
	Panel Beating		<i>525</i>	\$900.00
	Spray Painting Charge		<i>✓</i>	\$1,000.00
	Remove/refix Door Part		<i>X</i>	\$90.00
	Check Wiring		<i>X</i>	\$60.00
	TOTAL LABOUR		1525	\$2,050.00
	ESTIMATE TOTAL		1852.82	\$6,226.62
			<i>LS \$1500</i>	
			<i>03 days</i>	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Handwritten notes:
 92495745
 up 12/8/2022 4pm
 03 days
 c/s rising after repair
 fuphi C. Chantawan

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer
 Signature:
 Date: