

Date: 16/08/2022
 Vehicle No: SMQ7753X
 Model: TOYOTA VIOS 1.5E
 Chassis: MR2B23F3701194292-2019
 Reg.Year: 2019

Not Withdraw
6/1 Pay @ 3550/h
Account After Pain
8 days

Third Party Insurer: AIG
 Third Party Veh No: SFZ5246S
 Date of Accident: 07/08/2022
 Estimator: TING AN
 Surveyor:

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR TAIL LAMP LH	1		Per \$390.00
2	REAR WINDSCREEN MOULDING	1		Per \$95.00
3	REAR BUMPER	1		Per \$545.00
4	REAR BUMPER SIDE BRACKET LH	1		Per \$155.00
5	REAR BUMPER SEAL LH	1		Per \$75.00
6	REAR TAIL LAMP BRACKET LH	1		Per \$60.00
7	REAR BUMPER REFLECTOR LH	1		Per \$98.00
8	REAR FENDER LH	1		Per \$907.00
9	REAR RIM LH	1		Per \$1,891.00
10	REAR ABSORBER LH	1		Per \$150.00
11	REAR WHEEL BEARING HUB LH	1		Per \$849.00
SUB TOTAL				\$5,215.00
LESS 25%				-\$1,303.75
PARTS TOTAL				\$3,911.25

X
 ✓
 ✓
 ✓
 X
 X
 ✓
 ✓
 ✓

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR BUMPER CLIPS	1		Per \$50.00
2	REAR WINDSCREEN SEALANT	1		Per \$80.00
3	REAR FENDER SHEILD CLIPS LH	1		Per \$30.00
S/N TOTAL				\$160.00

✓
 ✓
 X

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX & READJUST REAR ACCIDENT AREAS & ETC. \$600.00 ✓

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR BUMPER, REAR FENDER LH & ETC. \$600.00 400

LABOUR CHARGES TO REMOVE & REFIX REAR FENDER INNER TRIM LH & CUSHION UPHOLDSTERY SET & ETC. TO EFFECT REPLACE OF REAR FENDER LH. \$300.00 100

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 16/08/2022
 Vehicle No: SMQ7753X
 Model: TOYOTA VIOS 1.5E
 Chassis: MR2B23F3701194292-2019
 Reg.Year: 2019

Third Party Insurer: AIG
 Third Party Veh No: SFZ5246S
 Date of Accident: 07/08/2022
 Estimator: TING AN
 Surveyor:

LABOUR CHARGES TO REMOVE & REFIX REAR WINDSCREEN GLASS, REAR WINDSCREEN MOUDLING, REAR WINDSCREEN SEALANT & ETC.	\$150.00	<i>120/</i>
LABOUR CHARGES TO REMOVE & REPLACE REAR RIM LH, REAR ABSORBER LH, REAR WHEEL BEARING HUB LH & ETC.	\$250.00	<i>120/</i>
TO WHEEL ALIGNMENT & BALANCING.	\$80.00	<i>20/</i>
TO TUFF KOTE & UNDERSEAL MATERIALS.	\$120.00	<i>30/</i>
TO CHECK WIRING & ELECTRICAL SYSTEM & ETC.	\$80.00	<i>20/</i>

LABOUR TOTAL	\$2,180.00
--------------	------------

TING AN	TOTAL	\$6,251.25
---------	--------------	-------------------

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: