



Motor Claim Department
United Overseas Insurance Limited
146 Robinson Road
#0-01 UOI Building
Singapore 068909

Josephine Wong@UOI.com.sg

16 August 2022

ck 96536619

Dear Sir / Madam

RE: DFSK, Vehicle Reg.No: GBL8926P

We are pleased to submit Finalization for the repair of the above-mentioned vehicle:

A) Labour Description	\$	Labour Cost
1 Remove, install & renew :- Front Lh fender, Lh headlamp, fender liner, Front Lh door, Lh rocker panel, Fender Grills, wind mirror, door window Pillar B, Lh sliding door .		3,600.00
2 Panel beating for Rocker panel inner, Pillar B, Lh Sliding door, and Lh quarter panel (Remove & Refit)		3,200.00
3 Computer Wheel Alignment - All 4 Wheels		200.00
4 Transfer door fitting and window mechanism to new door		800.00
5 Secure security area for Electric vehicle unplug OEM with release current		1,800.00
6 Respray premier & paint: Front Lh fender, Lh front door, Lh Sliding Door, Rocker panel, B pillar, Center pillar, Lh quarter panel and surface rear bumper		4,200.00

B) Parts	Qty	
1 Front Lhs door	1	\$ 678.42
2 Front Lhs door inner trim	1	\$ 265.85
3 Front Lh door window	1	\$ 99.35
4 Front Lh door window outer grille	1	\$ 41.17
5 Front Lh door outer handle	1	\$ 36.52
6 Front Lh door window regulator	1	\$ 124.73
7 Front Lh door window motor	1	\$ 220.56
8 Side mirror LH assy	1	\$ 148.10
9 Side mirror Lh inner cover	1	\$ 22.00
10 Front Lh wheel mudguard	1	\$ 42.31
11 Front Lh Door inner window run moulding	1	\$ 89.90
12 Front Lh door window run channel	1	\$ 49.76
13 Front Lh door upper hinge	1	\$ 32.40
14 Front Lh door lower Hinge	1	\$ 32.40

15	Lh rocker panel / <i>OK</i>	1	\$	2,373.70	✓
16	Lh pillar B (between frt door and sliding dr) / <i>OK</i>	1	\$	1,987.90	✓
17	Front Lh door lock / <i>X nn</i>	1	\$	48.99	
18	Front Lh door speaker JBL / <i>X nn</i>	1	\$	230.00	
19	Front Lh door visor <i>X nn</i>	1	\$	35.00	
20	Front Door Step / <i>OK</i>	1	\$	30.15	✓
21	Front Rest Panel <i>X nn</i>	1	\$	40.24	
22	Front door clips / <i>OK</i>	12	\$	60.00	✓
23	<i>Sliding door LH / OK</i>			<i>695.91</i>	✓
24					
25					
26					
27					
28					
29					
30					
31					

TOTAL:

Total Labour	\$	12,000.00
Total Parts	\$	6,689.45
	\$	18,689.45
Plus 7% GST	\$	1,308.26
Grand Total	\$	19,997.71

Should this repair job require any additional parts, we will inform you and bill you accordingly.
Please confirm your acceptance of this quotation by sending us a return fax with your signature and company stamp on it.

Yours sincerely,

I agree and accept the above quotation.

Workshop Department

Signature & Company stamp

Stere (LKK)

16/8/22, 3:30pm

8322 8813

sterechn@lkkauh.com

OK-M AL
EXCISE?

P/P

My Bel My

14 dys

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer