

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0701/2022/EQ
DATE : 16-Aug-22
WIP : 37551

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 16/08/2022

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Steve

8 days exclude 1 Sunday

31-Oct-22

OWNER'S NAME : MS TAI YIN LENG
ADDRESS : BLK 143 PASIR RIS GROVE
#10-60
SINGAPORE 518136
TELEPHONE : HP +65 97327446
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7210078477-01
VEHICLE NO : **SNA 9612 D**
MODEL CODE : Q3 1.4 TFSI S TRONIC
MODEL YEAR : 26/7/2021
ENGINE NO : CZD C40462
CHASSIS NO : WAUZZZF39M1120248
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 13-Aug-22
PLACE OF ACCIDENT : STILL ROAD S

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SNA 9612 D

S/N	NATURE OF JOBS		ESTIMATED CHARGES		SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$	480.00	\$	480.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	400.00	\$	400.00
3	TO REMOVE AND REINSTALL AIRCON CONDENSER, CHARGE AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM.	S/N \$	1,600.00	\$	1,600.00
4	TO CARRY OUT VACUUM AND REGAS FOR R1234.	S/N \$	1,200.00	\$	1,200.00
5	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND RHS HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED. (Q3 L/C - 3 days)	\$	4,800.00	\$	2,500.00
TOTAL LABOUR CHARGES		:	\$ 8,480.00	\$	6,180.00

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SNA 9612 D

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
	<i>c/f</i>		\$ 6,180.00
6	TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER.	\$ 2,500.00	\$ 1,100.00
7	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		: \$ 11,172.00	\$ 7,472.00

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNA 9612 D

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT		REMARKS
1	FRONT BUMPER	1	\$	1,073.00	\$ 858.40
2	FRONT BUMPER CONNECTING PIECE	1	\$	162.00	
3	FRONT BUMPER CLOSING ELEMENT - RH	1	\$	66.00	\$ 52.32
4	FRONT BUMPER GRILLE - CENTER	1	\$	242.00	\$ 193.60
5	FRONT BUMPER LOWER GRILLE COVER	1	\$	58.00	
6	FRONT BUMPER GRILLE - RH	1	\$	124.00	\$ 98.80
7	FRONT BUMPER CLOSING ELEMENT	1	\$	212.00	
8	FRONT BUMPER SPOILER	1	\$	426.00	\$ 340.80
9	AIR GUIDE GRILLE - RH	1	\$	171.00	\$ 136.40
10	RADIATOR GRILLE	1	\$	1,594.00	\$ 1,275.20
11	FRONT STRIKER PLATE	1	\$	271.00	\$ 216.80
12	FRONT S-LINE EMBLEM	1	\$	47.00	
13	FRONT "360" CAMERA COVER CAP	1	\$	46.00	\$ 36.88
14	FRONT "360" CAMERA BRACKET	1	\$	37.00	
15	FRONT "360" CAMERA	1	\$	1,264.00	
16	FRONT FOAM FILLER PIECE	1	\$	114.00	
17	FRONT BUMPER CARRIER	1	\$	974.00	\$ 778.80
18	FRONT BUMPER GUIDE SECTION - RH	1	\$	43.00	
19	FRONT BUMPER TOP COVER	1	\$	137.00	\$ 109.60
20	CAUTION SIGN STICKER	1	\$	16.00	\$ 12.40
SUB TOTAL SPARE PARTS		:	\$	7,077.00	\$ 4,110.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNA 9612 D

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
		<i>c/f</i>		\$	4,110.00
21	AIR CONDITIONER STICKER	1	\$ 9.00	\$	6.64
22	FRONT PARKING AID SENSOR	3	\$ 797.00		
23	FRONT PARKING AID SEAL RING	4	\$ 10.00		
24	FRONT BUMPER WIRING SET	1	\$ 750.00		
25	FRONT FENDER - RH	1	\$ 1,445.00	\$	1,156.00
26	FRONT FENDER ATTACHMENT PARTS	1	\$ 66.00		
27	FRONT FENDER BRACE - RH	1	\$ 98.00		
28	FRONT FENDER BRACKET - RH	1	\$ 39.00		
29	FRONT FENDER CLOSING ELEMENT - RH	1	\$ 37.00		
30	HEADLIGHT MOUNTING - LH / RH	2	\$ 264.00	\$	210.40
31	HEADLIGHT - RH	1	\$ 5,952.00	\$	4,761.60
32	HEADLIGHT HOSE - RH	1	\$ 28.00		
33	LIFT CYLINDER - RH	1	\$ 231.00	\$	184.40
34	LIFT CYLINDER HOSE	1	\$ 92.00		
35	LOCK CARRIER	1	\$ 1,412.00	\$	1,129.60
36	OUTSIDE TEMPERATURE SENSOR HOLDER	1	\$ 9.00		
37	RADIATOR COOLANT	6	\$ 297.00	\$	237.12
38	AIR GUIDE - LH / RH	2	\$ 86.00	\$	34.08
39	AIR GUIDE - UPPER / LOWER	2	\$ 96.00	\$	37.84
40	FRONT WHEEL HOUSING LINER - RH	1	\$ 260.00		
SUB TOTAL SPARE PARTS		:	\$ 11,978.00	\$	11,867.68

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNA 9612 D

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
		<i>c/f</i>		\$ 11,867.68
41	FRONT FENDER COVER - RH	1	\$ 18.00	
42	FRONT WHEEL ARCH COVER - LH / RH	2	\$ 566.00	\$ 452.00
43	FRONT NO PLATE	S/N	\$ 60.00	\$ 60.00
44	Added parts - see attached		\$ 605.00	\$ 483.60
45	SUNDRIES		\$ 400.00	
TOTAL SPARE PARTS		:	\$ 20,704.00	\$ 12,863.28
TOTAL LABOUR CHARGES		:	\$ 11,172.00	\$ 7,472.00
GRAND TOTAL		:	\$ 31,876.00	\$ 20,335.28

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.
 BL-14/10/22

PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg



Supplementary Estimate-1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0701/2022/EQ 19-Aug-22 CHANG 1 of 1 SNA 9612 D AUDI Q3 1.4 TFSI	
Quantity	Description		Unit Price	Amount
<u>Parts</u>				
1	A/C CONDENSER	BT 1	\$ 605.00	\$ 483.60
GRAND TOTAL			\$ 605.00	\$ 483.60

For Premium Automobiles Pte Ltd

Authorised Signature