

PEGASUS
ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From :

PEGASUS ENGINEERING & TRADING PTE LTD
 74 KIAN TECK ROAD
 SINGAPORE 628800

Officer in Charge : VIVIAN TAN EE WI
 Tel :
 Email :

Customer :

GRAB RENTALS PTE LTD
 3 MEDIA CLOSE #07-03
 SINGAPORE 138498

Attn :
 Tel :
 Fax No. :

Quotation No. : QO22/08-1076	Quotation Date : 13/08/2022	Terms : 60 DAYS
Vehicle No. : SLK7112P	Chassis No. : JM6BN22A8H0136163	Policy Number :
Model : MAZDA 3		Date of Accident : 12/08/2022
Third Party Insurer : SMRT		TP Vehicle No. : SHC4929J
Remarks :		

ITEM	DESCRIPTION	Qty	UNIT PRICE	AMOUNT (SGD)
			B/F	0.00
23	FRONT A-PILLAR PANEL (LHS) - REPAIR X NN	1		
24	REAR WINDSCREEN GLASS MOULDING / M	1	200.0000	200.00 98 ✓
25	LESS 20%	1	-1,793.4000	-1,793.40
26	REAR FENDER CLEAR STICKER (LHS) - M	1	25.0000	25.00 ✓
27	REAR WHEEL HUP CAP (LHS) - M	1	120.0000	120.00 100 ✓
28	REAR WINDSCREEN GLASS SEALANT - M	1	80.0000 40 ✓	80.00
29	FRONT WHEEL HUP CAP (LHS) - M	1	120.0000	120.00 100 ✓
30	TO REMOVE & REFIX BACK REAR WINDSCREEN GLASS.	1	200.0000 120	200.00
31	TO REMOVE & RESTORE BACK INNER TRIMMINGS, GARNISHES, SEAT AND ROOF LINING FOR FACILITATE REPAIR.	1	150.0000 50	150.00
32	TO REMOVE & TRANSFER BOTH DOOR MECHANISM TO THE NEW DOOR.	1	200.0000 100	200.00
33	TO APPLY RUSTPROOFING / TUFFCOATING TREATMENT TO REPLACED PARTS.	1	120.0000 30	120.00
34	TO CONDUCT WHEEL ALIGNMENT.	1	150.0000 80	150.00
35	TO KNOCKING & PANEL BEATING.	1	1,200.0000 /	1,200.00
36	TO PUTTY & SPRAY PAINT ON THE AFFECTED AREAS.	1	1,600.0000 1200	1,600.00

Steve (LKK)
 16/8/22, 1.17p

M R
 L/S
 by ALY
 10 Lys

supp - 310

7244.60

L/S - 5795.68
 = 5800

Sub Total 11,138.60
 GST(7.00%) 779.70
 Total (SGD) 11,918.30

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- Please conduct the survey at Pegasus Engineering @ 74 Kian Teck Road Singapore 628800
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer