



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2SINGAPORE 018983 ATTN: OH VALE			Ref: CS/ASM22007825/Gcy3e2 Date: 04/04/2023 Code: HSB	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHA 9567Y	Veh. Inspected	FBL 8873H
	Policy No.	VFX/P2419140	Coverage (\$)	0.00
	Claim No.	S2M0476S	Excess (\$)	0.00
	Assign From	OH VALE	Assign Date	16/08/2022
2. Vehicle Particulars & Condition				
	Make & Model	HONDA CBF190X	c.c	184
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	LALPJL702H3017415	Colour	SILVER
	Odometer	9645 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	110/70-17	DUNLOP	5 mm
	L/H Front Tyre			mm
	R/H Rear Tyre	150/60-17	DUNLOP	5 mm
	L/H Rear Tyre			mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	19/07/2022	Inspection Date	16/08/2022
	Survey held at	ERZAT LEE MOTOR TRADING PTE LTD 25 KAKI BUKIT ROAD 4, #03-37, SYNERGY @ KB, SINGAPORE 417800		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	