



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2SINGAPORE 018983 ATTN:KHOR SAW THENG		Ref: CC4/ASM22007833/Apa3q2 Date: 14/04/2023 Code: HSB	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHD 261Y	Veh. Inspected	GBB 631U
Policy No.	P2459880	Coverage (\$)	0.00
Claim No.	S2M048XX	Excess (\$)	0.00
Assign From		Assign Date	16/08/2022
2. Vehicle Particulars & Condition			
Make & Model	mitsubishi center	c.c	2977
Engine No.	HIDDEN	Year of Reg.	2008
Chassis No.	FB70BBA10514	Colour	WHITE
Odometer	461635 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	185/75 R15	BRIDGESTONE	6 mm
L/H Front Tyre	185/75 R15	BRIDGESTONE	6 mm
R/H Rear Tyre	185/75 R15	BRIDGESTONE	6 mm
L/H Rear Tyre	185/75 R15	BRIDGESTONE	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	12/08/2022	Inspection Date	16/08/2022
Survey held at	8 KAKI BUKIT AVENUE 4, #04-48 PREMIER@KAKI BUKIT		
Repairer	KS AUTOMOBILE		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		9 Working Days	