

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 62907
Date Estimated : 15/08/2022
Prepared By : Han Kwan Yong

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -

Tony Tan Kim Chin
39 Jalan Limau Purut

- ACCOUNT - 40000

Cash Sales - Service
Singapore

Singapore 468213

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJQ3313U	WBAJA520X0G454773	28/03/2017	530ia	49059

DESCRIPTION	VALUE
To replace rear bumper, boot lid, carbon spoiler and to knock out dented are	2125 2,975.00
To respray rear bumper and boot lid	1972 2,076.00
To carry out body cavity preservation. (Per panel).	112 118.00
To transfer lock mechanism from old to new bootlid including conduct check on new bootlid central locking system for proper function.	544 531.00
To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct check for proper function.	168 177.00
To check electrical wiring system and lighting at the rear section for proper function.	168 177.00
Sundries.	150.00

Total Labour 1: 6,204.00

DESCRIPTION	QTY	PRIC	VALUE
TAILGATE ALUMINIUM	1	1,845.85	1,845.85
# REAR BUMPER CARRIER	1	909.65	909.65
# EXHAUST SUPPORT	1	118.00	118.00
REAR BUMPER COVER (M)	1	280.80	280.80
# REAR BUMPER CENTRE GUIDE (M)	1	215.85	215.85
# REAR BUMPER PANEL PRIMED (M)	1	1,627.00	1,627.00
LETTERING 530I	1	65.60	65.60
PLAQUE 74MM	1	72.85	72.85
# LETTERING M5	1	83.80	83.80
GROMMET	2	0.80	1.60
# M PERFORMANCE REAR SPOILER C	1	1,617.15	1,617.15
UNDERBODY PANELLING REAR	1	49.70	49.70

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Tampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

115, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 62907

Page No. : 2 of 5

Date Estimated : 15/08/2022

Prepared By : Han Kwan Yong

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJQ3313U	WBAJA520X0G454773	28/03/2017	5301A	49059

DESCRIPTION	QTY	PRIC	VALUE
TRUNK LID GASKET	1	131.25	131.25
(DG/SL) ADHESIVE SET 1K 80ML	1	107.55	107.55
Total Parts :			7,126.65

Ster (LKR)

6/9/22, 11.30am

WLR

S Lys
P/P

17 BL Y

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Labour 1	:	6,204.00
Parts	:	7,126.65
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	933.15
Grand Total	:	14,263.80

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **