

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	LONPAC INSURAN	NCE BHD	R	Ref:	CS3/LPC22007839/y3	
	300 BEACH ROAD #17-04/07 THE CO	NCOURSESINGAPORE 199555	D	Date:	16/08/2022	
			C	Code:	LPC2	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	XD 9463H	Veh. Inspected		GZ 3637Z	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	21/22/22/VC00/026156	Excess (\$)		0.00	
	Assign From	ONG LI LI	Assign Date		16/08/2022	
2. Vehicle Particulars & Condition						
	Make & Model		c.c		0	
	Engine No.	HIDDEN	Year of Reg.			
	Chassis No.		Colour			
	Odometer	-	Steering			
	Brakes		Modification			
	General					
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre				mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre				mm	
	L/H Rear Tyre				mm	
4.	Description of Damages					
5.	General Information					
	Accident Date	15/08/2022	Inspection Date			
	Survey held at	TAN ENG HUAT MOTOR				
		BLK 6 DEFU LANE 10 #01-556 . SINGAPORE 539187				
5a. Remarks						
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.					