



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (S) PTE LTD
4 SHENTON WAY #21-01
SGX CENTRE 2 SINGAPORE 068807

Ref: CS/MSG22007852/Uqy3

Date: 17/08/2022

Code: MSG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLN 143E	Veh. Inspected	GBD 8776Y
Policy No.	30001960892	Coverage (\$)	0.00
Claim No.	281783	Excess (\$)	0.00
Assign From	DOUGLAS ONG	Assign Date	17/08/2022

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	13/08/2022	Inspection Date	17/08/2022
Survey held at	LIU'S BROTHER AUTO WORK SHOP 1 KAKI BUKIT AVENUE 6 #01-01 AUTO BAY @ KAKI BUKIT SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--