

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref: 22.29949 Date: 30<sup>th</sup> Nov 2022

Our Ref: CS3/ASM21001402/Rqy3e2-1

## M/s Axa Insurance Pte Ltd

C/o Seah Ong & Partners LLP 36 Robinson Road #12-03 City House Singapore 068877 (The Motor Claims Department)

Dear Sir / Madam,

## EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: JRC 6736

INSURED VEHICLE: SHA 6049X ACCIDENT DATE: 23/01/2021

We thank you for your instruction on 14/08/2022.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of JRC 6736 from M/s KTO Automobile Assessors.
- b) Singapore Accident Statement of Vehicles SHA 6049X.
- c) Police Report of Vehicles JRC 6736 and SHA 6049X
- d) Final Repair Bill of JRC 6736 from M/s Dynasty Motor Pte Ltd.
- e) Colour damaged vehicle photographs of JRC 6736.

Pre-Repair Inspection Date: 29/01/2021 at M/s Dynasty Motor Pte Ltd, 50 Bukit Batok St 23 #01-24 Midview Building, Singapore 659578.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number : JRC 6736

Make & Model : Yamaha 135 LC

Year of Registration : 2015 Chassis Number : -Engine Capacity : -

- 2. We recommend that the repairs of the entire damage require about <u>5 (Five)</u> working days to complete.
- 3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.