



樹發汽車修理廠 SHU FATT AUTO WORKS

BLOCK 1009 BUKIT MERAH LANE 3 #01-90 SINGAPORE 159723 TEL: 6273 0119 FAX: 6270 7065

Email: shufatt@pacific.net.sg

Co. Reg. No. 09062400M GST Reg. No. 09-062400-M

Our Ref: WSK/jw/SF-quo
15th August 2022

Supplementary

Sompo Insurance Singapore Pte Ltd
(Third Party)

SKL 8192 H MERCEDES BENZ E250

Spare Parts	1	Left rear bumper inner mounting
	1	Rear bumper inner centre garnish
	10	rear bumper centre garnish rivets. @\$5.50

	SS		
BR	72.00	nett	✓
BR	94.00	nett	✓
NEL	55.00	nett	✓ 30
221.00			