



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Ref: CS/FCI22007877/Ucy3e2 Date: 30/08/2022 Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SMB 353S	Veh. Inspected	SMJ 262D
Policy No.	D-22099187MFBP	Coverage (\$)	0.00
Claim No.	D22002555MFBP	Excess (\$)	0.00
Assign From	HARMINDER KAUR	Assign Date	17/08/2022
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA SIENTA (A)	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	MHFZ28H3400062360	Colour	SILVER
Odometer	52905 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	185/60 R15	PREMIO	7 mm
L/H Front Tyre	185/60 R15	PREMIO	7 mm
R/H Rear Tyre	185/60 R15	PREMIO	7 mm
L/H Rear Tyre	185/60 R15	PREMIO	7 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	15/08/2022	Inspection Date	18/08/2022
Survey held at	CONVERGENCE AUTOMOTIVE PTE LTD 39 WOODLANDS CLOSE, #01-24, MEGA@WOODLANDS SINGAPORE 737856		
5a. Remarks			
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	