



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

SOMPO INSURANCE SINGAPORE PL

INV No. AC2206323

50 RAFFLES PLACE #03-03
SINGAPORE LAND TOWER
SINGAPORE 048623

INV Date 11/10/2022
Reference CS3/SMO22007917/TEcy3m
Code SMO

PROFESSIONAL SERVICE FEE

Vehicle No. SLV 7564K

Insured Veh. GBH 4978L

Claim No. CMTD2202833/AGC

Policy No.

Accident Date 12/08/2022

Inspection Date 22/08/2022

Description	Total
Pre-Repair Survey as per NIMA Protocol 2016 Admt 1 (Photo taking + Transport)	100.00
Parts dismantled before repair as per NIMA Protocol (Photo taking + Transport on 23.08.2022)	10.00
Subtotal	110.00
GST (7%)	7.70
Grand Total	117.70

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

SML