

SM AUTOMOTIVE

Blk 1 Kaki Bukit Ave 6 Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883

8/9/2000

01-43

Email: SM_AUTOMOTIVE@HOTMAIL.COM

Singapore 417883

Tel: (65) 6747 9241

Fax: (65) 6741 7276

RCB No: 53231488C

GST Reg No : 53231488C

TP A x 4
Xiao Tony

Accident date: 27/07/2022

Estimated repair cost for vehicle no: SLQ8468A HYUNDAI TUCSON 1.6GLS T-GDI
DCT 2WD

CHASSIS: KMHJ3812VJU529465 (2017)

S/n	Qty	Items	U/price	Amount
1	1	FRONT BUMPER <i>deduct</i>	\$ 645	\$ 645 ✓
2	1	FRONT BUMPER REINFORCEMENT <i>HE in</i>	\$603.60	\$603.60 +
3	1	FRONT BUMPER SPONGE <i>from car</i>	\$ 135	\$ 135 ✓
4	1	FRONT BUMPER LOWER SPOILER <i>HE in</i>	\$381.40	\$381.40 +
5	1	FRONT BUMPER SIDE RETAINER LH <i>deduct</i>	\$12.00	\$12.00 ✓
6	1	FRONT BUMPER FOG LAMP LH <i>auto</i>	\$256.70	\$256.70 ✓
7	1	FRONT BUMPER FOG LAMP OUTER GARNISH LH <i>HE in</i>	\$28.00	\$28.00 +
8	1	FRONT BUMPER DAYLIGHT LH <i>auto</i>	\$598.40	\$598.40 ✓
9	1	FRONT FENDER OUTER GARNISH LH <i>HE in</i>	\$195.00	\$195.00 +
10	1	FRONT BUMPER SENSOR <i>deduct</i>	\$170.00	\$170.00 ✓
<i>Front Bumper Undercover torn</i>			<i>285</i>	
			TOTAL :	\$2,833.80
			LESS 20 %	\$566.76
			SUB-TOTAL :	\$2,267.04
			<i>2297.10</i>	
			<i>1837.68</i>	

S/N	Qty	ITEMS / SPECIAL NETT	U/price	Amount
1	1	FRONT BUMPER CLIPS <i>HE in</i>	\$80.00	\$80.00 30
2	1	FRONT BUMPER FOG LAMP OUTER CHROME LH <i>auto</i>	\$450.00	\$450.00 30
3	1	FRONT FENDER OUTER GARNISH CLIPS LH <i>HE in</i>	\$60.00	\$60.00 +
			TOTAL:	\$590.00
			<i>330</i>	
			TOTAL PARTS :	\$2,857.04

Labour charges

1	LABOUR FOR PANEL BEATING	\$800.00
2	LABOUR FOR SPRAYPAINTING	\$600.00
4	WIRING CHECK	\$80.00
5	TO APPLY TUFF COATING/RUST PROOF ACCIDENT AREAS	\$150.00

6 *to remove front bumper sensor.*

to remove front bumper sensor.
LKR Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Subtotal :- \$1,630.00

Total:- \$4,487.04

total: 2777.68
h/s: 2.2K
(2.2K)

Adrian Lj
h/s 08/05/22
03 Days