

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER <i>Rehd</i>	1	\$ 595.90	\$ 595.90
2	FRONT BUMPER SIDE RETAINER RH <i>Rehd Rngd</i>	1	\$ 67.30	\$ 67.30
3	HEAD LAMP RH <i>Ct</i>	1	\$ 981.00	\$ 981.00
4	FRONT CORNER PANEL RH <i>Reps</i>	1	\$ 342.00	\$ 342.00
5	FRONT WINDSCREEN MOULDING <i>Men</i>	1	\$ 192.50	\$ 192.50
6	FRONT DOOR RH <i>Rehd</i>	1	\$ 1,490.10	\$ 1,490.10
7	FRONT DOOR INNER RUBBER RH <i>3M</i>	1	\$ 199.70	\$ 199.70
8	FRONT DOOR OUTER MOULDING RH <i>3M</i>	1	\$ 168.60	\$ 168.60
9	FRONT DOOR HINGE RH <i>3M</i>	2	\$ 98.70	\$ 197.40
10	FRONT DOOR CHECKER RH <i>3M</i>	1	\$ 138.10	\$ 138.10
11	FRONT DOOR WEATHER STRIP RH <i>Men</i>	1	\$ 199.40	\$ 199.40
12	FRONT DOOR INNER LOCK RH <i>3M</i>	1	\$ 299.50	\$ 299.50
13	FRONT DOOR LOCK CATCH RH <i>3M</i>	1	\$ 42.10	\$ 42.10
14	FRONT DOOR INNER TRIM BOARD RH <i>3M</i>	1	\$ 942.60	\$ 942.60
15	FRONT DOOR ARCED RUBBER RH <i>3M</i>	1	\$ 342.60	\$ 342.60
16	FRONT DOOR SPEAKER RH	1	\$ 306.10	\$ 306.10
17	FRONT DOOR PILLAR (OUTER) RH <i>Reps</i>	1	\$ 947.60	\$ 947.60
18	FRONT DOOR SIGNAL RH <i>Men</i>	1	\$ 164.80	\$ 164.80
19	FRONT SHOCK ABSORBER RH <i>2</i>	1	\$ 359.60	\$ 359.60
20	FRONT KNUCKLE ARM RH <i>3M</i>	1	\$ 411.10	\$ 411.10
21	FRONT KNUCKLE BEARING HUB RH <i>3M</i>	1	\$ 189.20	\$ 189.20
22	FRONT UPPER ARM RH <i>3M</i>	1	\$ 611.10	\$ 611.10

TO : **INDIA INTERNATIONAL** MOTOR CLAIMS DEPTS
 VEHICLE NO : **GBJ190H**
 MODEL : **KIA K2500**
 DATE OF ACCIDENT : **13.08.2022**
 TIME OF ACCIDENT : **09:15HRS**

23	FRONT LOWER ARM RH <i>the m</i>	1	\$ 491.10	\$ 491.10	<i>x.</i>
----	---------------------------------	---	-----------	-----------	-----------

2098.20
1888.38

TOTAL PRICE \$ 9,679.40
 LESS ~~25%~~ 10% \$ 2,419.85
 SUB TOTAL PRICE \$ **7,259.55**

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	FRONT NUMBER PLATE <i>x</i>	1	\$ 50.00	\$ 50.00	<i>x.</i>
2	FRONT DOOR SEALANT <i>the m</i>	1	\$ 80.00	\$ 80.00	<i>+</i>
3	FRONT DOOR LTA STICKER <i>the m</i>	1	\$ 40.00	\$ 40.00	<i>30</i>
4	FRONT DOOR INNER TRIM BOARD CLIP <i>the m</i>	1	\$ 50.00	\$ 50.00	<i>+</i>
5	FRONT DOOR PILLAR INNER GARNISH CLIP <i>the m</i>	1	\$ 30.00	\$ 30.00	<i>+</i>
6	FRONT WHEEL TYRE RH <i>get</i>	1	\$ 250.00	\$ 250.00	<i>+</i>
7	FRONT WHEEL RIM RH <i>get</i>	1	\$ 350.00	\$ 350.00	<i>+</i>
8	BRAKE OIL <i>the m</i>	1	\$ 60.00	\$ 60.00	<i>x</i>

30

TOTAL \$ 910.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	TO PANEL BEAT, WELD ,CUT, ADJUST, KNOCK	\$ 1,800.00	<i>400.</i>
2	TO PUTTY, SPRAY PAINT, POLISH WAX	\$ 1,600.00	<i>300</i>
3	TO SPRAY TUFF COAT	\$ 250.00	<i>30</i>
4	WIRING, BULB CHECKING	\$ 60.00	<i>30</i>
5	REMOVE AND REFIX UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	\$ 350.00	<i>x</i>
6	CONDUCT WATER TER LEAKAGE TEST	\$ 80.00	<i>x</i>
7	TRANSFER FRONT DOOR MECHANISM RH	\$ 80.00	<i>40</i>
8	REMOVE AND REINSTALL WINDOW GLASS RH	\$ 60.00	<i>40</i>
9	REMOVE AND REFIX FRONT WINDSCREEN GLASS	\$ 120.00	<i>x.</i>

TO : INDIA INTERNATIONAL MOTOR CLAIMS DEPTS
VEHICLE NO : GBJ190H
MODEL : KIA K2500
DATE OF ACCIDENT : 13.08.2022
TIME OF ACCIDENT : 09:15HRS

10	REFOCUS HEADLAMP BEAM	\$ 60.00	x
11	REMOVE AND REFIX FRONT UNDERCARRIAGE	\$ 650.00	x
12	FOUR WHEEL ALIGHMENT	\$ 80.00	x
13	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS,RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	x

840

TOTAL \$ 5,370.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 8,169.55
TOTAL LABOUR COST : \$ 5,370.00
TOTAL REPAIR COST : \$ 13,539.55

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
IRENE
HP : 8297 9787

Adrian Lj
H/S 18/08/22.

OK & Rep.

Total : 2758.38

H/S: 2.2K.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: