

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SHC7262D
MAKE HYUNDAI
MODEL I40

DATE: 17.08.22
MVA JUMANI
DOA: 16.08.22

NTUC

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	BOOTLID COVER / Blue			\$2,609.80
1	REAR BUMPER ASSY / RL			\$553.00
1	REAR BUMPER UNDER COVER / RL / Cst.			\$228.00
1	REAR BUMPER BEAM / NN			\$428.40
10	REAR BUMPER CLIPS / MC			\$22.00
1	BOOTLID MOULDING / Cst.			\$85.00
1	BOOTLID LOWER GARNISH / RL / Cst.			\$227.90
1	BOOTLID EMBLEM - I40			\$67.90
1	BOOTLID EMBLEM - CRDI			\$52.40
1	BOOTLID EMBLEM - H			\$63.10
SUB TOTAL				\$4,337.50
LESS 20%				\$867.50
DISCOUNTED TOTAL				\$3,470.00
REAR NUMBER PLATE / Cst.				\$50.00
REVERSE SENSOR / RL				\$135.70
REAR BOOTLID COMFORT LOGO / MC				\$30.00
REAR BOOTLID TEL.NOS LOGO / MC				\$30.00
REAR BOOTLID APPS LOGO / RL				\$40.00
REAR BUMPER MAT / RL				\$50.00
Labour Charge				\$335.70
PANEL BEATING				\$1,100.00
SPRAY PAINT				\$600.00
REMOVE / REFIX REVERSE SENSOR				\$50.00
CHECK WIRING				\$50.00
TOWING				\$60.00
				\$1,860.00
TOTAL LABOUR				\$1,860.00
ESTIMATE TOTAL				\$5,665.70

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

-20%: 3650