



Letter of Claims
Request of direct settlement.

We are submitting a claim on behalf of our customer ARISTO MANGKUYONO
NRIC 8888443A insured of vehicle 5F28388X against
your insured vehicle number PC3446Y (ALLIANZ)
On the accident dated on 18/08/2022 (ddmmyyyy) along
TRAFFIC LIGHT Junction @ Bt BATOK road No. 3

Dated this 18 (day) of 08 (month) 20 22



Volkswagen Group Singapore
247 Alexandra Road
Singapore 159934
DID: 63057176/63057299
HP: 92361399
charmaine.kong@vw.com.sg

VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road
Singapore 159934
Biz. Reg. No.: 199101494Z
GST No.: M200985052



SKODA

Commercial
Vehicles

Quotation

Non binding - Preview

Page 1/2

Company
ALLIANZ GLOBAL
CORPORATE & SPECIALTY SE
SINGAPORE
12 MARINA VIEW
#14-01 ASIA SQUARE TOWER 2
Singapore 018961

Customer Details:
Mr
ARISTO
MANGKULIONO
620 BUKIT BATOK CENTRAL
#30-524
Singapore 650620

Document no.
Document date 18-08-2022
Customer no. 5211042669
Customer GST-ID T11FC0131K
Dealer 30001
Job order number 2022023997/ 1
Job order date 18-08-2022
Service Advisor YEN MEI WONG

License plate	Model code	First registration	VIN	Model	Mileage
SFZ8388X	5G13HZ	24-10-2017	WVWZZZAUZH127782	Golf 1.4 CLBM 92 TSI D7F	60,303

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
9801B004	B&P CHECK SHORT CIRCUIT / HARNESS REPAIR				#1	280.00	299.60
9801B005	B&P DIAGNOSIS AND PROGRAMMING				#1	480.00	513.60
5G6807417APGRU	Cover For Bumper Primed	1	pcs.	1,382.73	10.00% #1	1,244.46	1,331.57
5G6807568D 9B9	Rear Diffuser Satin Black	1	pcs.	349.21	10.00% #1	314.29	336.29
5G0919491	Sensor Bracket	2	pcs.	16.08	10.00% #1	28.94	30.97
5G0919491A	Sensor Bracket	1	pcs.	16.08	10.00% #1	14.47	15.48
5G0919492A	Sensor Bracket	1	pcs.	16.08	10.00% #1	14.47	15.48
D 180KU2A1	2k-Plastic Adhesive	1	pcs.	85.94	10.00% #1	77.35	82.76
D 822150A1	Bonding Agent For Plastic	1	pcs.	68.85	10.00% #1	61.97	66.31
5G0807305D	Bumper REINFORCEMENT	1	pcs.	732.39	10.00% #1	659.15	705.29
5G6807863C	Attachment Strip BUMPER CTR BRACKET	1	pcs.	70.74	10.00% #1	63.67	68.13
5G6807393A	Guide Piece LHR BUMPER BRACKET (UPPER)	1	pcs.	41.89	10.00% #1	37.70	40.34
5G6807394A	Guide Piece RHR BUMPER BRACKET (UPPER)	1	pcs.	41.89	10.00% #1	37.70	40.34
5G6807393	Guide Piece LHR BUMPER BRACKET (SIDE)	1	pcs.	41.89	10.00% #1	37.70	40.34
5G6807394	Guide Piece RHR BUMPER BRACKET (SIDE)	1	pcs.	41.89	10.00% #1	37.70	40.34
WHT005263	Rivet	4	pcs.	1.32	10.00% #1	4.75	5.08
	LABOUR	3	pcs.	720.00	#1	2,160.00	2,311.20
	SPRAY PAINT	3	pcs.	680.00	#1	2,040.00	2,182.80
	NAMBER PLATE	1	pcs.	80.00	#1	80.00	85.60
	MSIG MOTORMAX PLUS VS ALLIANZ 3RD PARTY VEHICLE PC3446Y D.O.A: 18-08-2022 SURVEY BY:						

Quotation valid till 25-08-2022

Tax Code	Labour	Material	Material Discount	GST %	GST	Total Discount	Total amount excl. GST	Total amount incl. GST
#1	760.00	6,914.32	292.70	7%	537.20	292.70	7,674.32	8,211.52
Total	760.00	6,914.32	292.70		537.20	292.70	7,674.32	8,211.52

VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road
Singapore 159934
Biz. Reg. No.: 199101494Z
GST No.: M200985052



SKODA

Commercial
Vehicles

Quotation

Non binding - Preview

Page 2/2

Company
ALLIANZ GLOBAL
CORPORATE & SPECIALTY SE
SINGAPORE
12 MARINA VIEW
#14-01 ASIA SQUARE TOWER 2
Singapore 018961

Customer Details:
Mr
ARISTO
MANGKULIONO
620 BUKIT BATOK CENTRAL
#30-524
Singapore 650620

Document no.
Document date
Customer no.
Customer GST-ID
Dealer
Job order number
Job order date
Service Advisor

18-08-2022
5211042669
T11FC0131K
30001
2022023997/ 1
18-08-2022
YEN MEI WONG

License plate	Model code	First registration	VIN	Model	Mileage
SFZ8388X	5G13HZ	24-10-2017	WVWZZZAUZHW127782	Golf 1.4 CLBM 92 TSI D7F	60,303

Customer



—VISIT OUR WEBSITE: aftersales.vw.com.sg (for online service appointments) and volkswagen.com.sg and www.skoda.com.sg (for additional services, products and promotions).—

All invoices are denominated in SGD, unless otherwise stated.