

VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road
Singapore 159934
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation

Non binding - Preview

Page

1/2

Company
ALLIANZ GLOBAL
CORPORATE & SPECIALTY SE
SINGAPORE
12 MARINA VIEW
#14-01 ASIA SQUARE TOWER 2
Singapore 018961

Customer Details:
Ms.
CHEN
XINYI GWENDOLYN
BLK 1 ZEHNDER ROAD
#01-02
SINGAPORE 117686

Document no.
Document date
Customer no.
Customer GST-ID
Dealer
Job order number
Job order date
Service Advisor
19-08-2022
5211042669
T11FC0131K
30001
2022024078/ 1
19-08-2022
Dass Anthonidas
Christopher

License plate	Model code	First registration	VIN	Model	Mileage
SNB837B	AD14N6R0	29-07-2021	WVGZZZ5NZLW393877	Tiguan R-Line 1.4 TSI 110kW N6 DSG	20

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
9801B004	B&P CHECK SHORT CIRCUIT / HARNESS REPAIR				#1	280.00	299.60
9801B005	B&P DIAGNOSIS AND PROGRAMMING				#1	480.00	513.60
5NA807421 GRU	Cover For Bumper Primed REAR BUMPER (UPPER)	1	pcs.	1,586.27	10.00%	1,427.64	1,527.57
5NA807521C GRU	Spoiler Primed BUMPER LOWER SPOILER	1	pcs.	436.50	10.00%	392.85	420.35
5NA807393	Guide Piece LHR BUMPER BRACKET (SIDE)	1	pcs.	45.25	10.00%	40.73	43.58
5NA807394	Guide Piece RHR BUMPER BRACKET (SIDE)	1	pcs.	45.25	10.00%	40.73	43.58
5NA807393A	Guide Piece LHR BUMPER BRACKET (OUTER)	1	pcs.	45.25	10.00%	40.73	43.58
5NA807394A	Guide Piece RHR BUMPER BRACKET (OUTER)	1	pcs.	45.25	10.00%	40.73	43.58
5NA807863	Attachment Strip REAR BUMPER BRACKET (CTR)	1	pcs.	70.74	10.00%	63.67	68.13
3Q0919275 GRU	Sensor Primed	4	pcs.	190.18	10.00%	684.65	732.58
3Q0919133 9B9	Seal Ring Satin Black	4	pcs.	4.72	10.00%	16.99	18.18
5NA919491	Sensor Bracket	1	pcs.	14.19	10.00%	12.77	13.66
5NA919491A	Sensor Bracket	1	pcs.	14.19	10.00%	12.77	13.66
5NA919492A	Sensor Bracket	1	pcs.	14.19	10.00%	12.77	13.66
5NA919492	Sensor Bracket	1	pcs.	14.19	10.00%	12.77	13.66
D 180KU2A1	2k-Plastic Adhesive	1	pcs.	85.94	10.00%	77.35	82.76
D 822150A1	Bonding Agent For Plastic	1	pcs.	68.85	10.00%	61.97	66.31
5NA807305A	Bumper REINFORCEMENT	1	pcs.	782.05	10.00%	703.85	753.12
5NA853835 2ZZ	Decorative Moulding Brigh BUMPER CHROME (CTR)	1	pcs.	233.76	10.00%	210.38	225.11
5NA853841 2ZZ	Decorative Moulding Brigh LHR BUMPER CHROME	1	pcs.	179.92	10.00%	161.93	173.27
5NA853842 2ZZ	Decorative Moulding Brigh RHR BUMPER CHROME	1	pcs.	183.84	10.00%	165.46	177.04
5NA807568C 041	Rear Diffusor Black	1	pcs.	559.44	10.00%	503.50	538.75
	LABOUR	1	pcs.	720.00		2,160.00	2,311.20
	Spray Painting	1	pcs.	680.00		2,040.00	2,182.80
	ALLIANZ DIRECT						
	DOA: 18/8/2022						
	TP VEH NO: SLR8256P						
	SURVEY BY:						

Quotation valid till 26-08-2022

VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road
Singapore 159934
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation

Non binding - Preview

Page 2/2

Company
ALLIANZ GLOBAL
CORPORATE & SPECIALTY SE
SINGAPORE
12 MARINA VIEW
#14-01 ASIA SQUARE TOWER 2
Singapore 018961

Customer Details:
Ms.
CHEN
XINYI GWENDOLYN
BLK 1 ZEHNDER ROAD
#01-02
SINGAPORE 117686

Document no.
Document date
Customer no.
Customer GST-ID
Dealer
Job order number
Job order date
Service Advisor
19-08-2022
5211042669
T11FC0131K
30001
2022024078/ 1
19-08-2022
Dass Anthonidas
Christopher

License plate SNB837B	Model code AD14N6R0	First registration 29-07-2021	VIN WVGZZZ5NZLW393877	Model Tiguan R-Line 1.4 I TSI 110kW N6 DSG	Mileage 20			
Tax Code	Labour	Material	Material Discount	GST %	GST	Total Discount	Total amount excl. GST	Total amount incl. GST
#1	760.00	8,884.24	520.43	7%	675.10	520.43	9,644.24	10,319.34
Total	760.00	8,884.24	520.43		675.10	520.43	9,644.24	10,319.34

Chris Anthonidas
Insurance Advisor
Tel: 6305 7299 Ext: 2 *Paul*
Mobile: 8511 2203
Service Advisor

Customer

—VISIT OUR WEBSITE: aftersales.vw.com.sg (for online service appointments) and volkswagen.com.sg and www.skoda.com.sg (for additional services, products and promotions).—

All invoices are denominated in SGD, unless otherwise stated

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Paul
Hp 90010068
3 days + 3 = 6 days
P/P
24/08/22 @ 0930
Resy before paid