

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SHC8999E

33.06.2022

MAKE REG 19.05.2016

MODEL I-40

CHIANG/ NTUC

Qty	Parts Description/ Labour	Type	300	Amount
1	FRONT BUMPER TOP BRACKET LH/RH		\$22.40	\$44.80
1	FRONT BUMPER			\$1,052.20
1	FRONT FENDER RH			\$663.00
1	HEAD LAMP RH			\$1,388.00
1	FRONT BUMPER GRILLE RH			\$187.20
10	BUMPER CLIPS		\$2.20	\$22.00
	SUB TOTAL			\$3,357.20
	LESS 20%			\$671.44
				\$2,685.76
1	FRONT FENDER ADVERTISEMENT			\$100.00
				\$100.00
	Labour Charge			
	Panel Beating			\$450.00
	Spray Painting Charge			\$600.00
	Tuff Kote			\$60.00
	Check Lighting			\$60.00
	TOTAL LABOUR			\$1,170.00
	ESTIMATE TOTAL			\$3,955.76

Thuan

82235764

6/6/22 1600

L/S 3dayswp

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: