ass. REC. BY: Thouan REF: Ntuc N9/M	1C22008000/Vgc
ASSIG	NMENT
244	Veh No: S+148044M Yr Regn: 3(15/17
From:	Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi) Prime Mover /
Estimated Cost: OD / TP / WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or
	Make: A toyofa prius c.c   748
To Inspect Vehicle No:	Make:  Colour  A/C: Insured / Std / NI / NA
at Workshop m/s	Sp.Reading 76/63 T/Radio: Insured / Std / NI / NA
of	Eng/No:
Insured:	C/No: 3TDKB3Fa403556986
Policy No.	Gen. Cond: Good / Fair / Poor / Burnt
Claims No Excess:	Steering: Inorder / Jammed / Leaked / Burnt or
Sum insured.	Brake: Inorder / Jammed / Leaked / Burnt or
(Client's Record) Make of Veh:	Modi: Nil /S/Rim / STD A/Rim or
IVIANG OI VOII.	Tyre Size: F: 195(55)p(6
(Policy Condition)	R: (95/85 145
Remark: The veh had commenced its  N/S  O/S	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO OF WEST AM
repair at the time of inspection.	A CONTRACTOR OF THE CONTRACTOR
Bal. or Market Value:	Front Rear R/Bal
IDAC Accident Rport: Consistent? : Yes or No	L/Bal. mm
GIA / PR Seen: Consistent? : Yes or No	D.O.A. HSPER 10/6/22 D.O.I. 10/6/22 16/55
Est Repairs: 2 days Res.: Yes or No	006-
Lum Sum: % 3 Val.: Yes or No	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
TO A DED / 24 HRS	
CA / REV / REP. / 24 HRS  Vehicle: IN / OUT	The U/C / Chassis frame / Body Structure affected due to collision.
Date:Person Contacted:	The 0/0 / Charter
Date / Time Action / Instruction	
lump sum: \$1500 and 2 days	
(red \$938.49.38%)	
(196) 953223, 6676)	
	Days Of Repair: 2
Date/Time, File Pass to? : Preli. Report	Resurvey No. of Trip:
1) 26/08/22 : Final Report	Transportation:
Date/Time, File Return to?	ee: : Site Insp (\$)S+RS,SI
2)	: Interview (\$) Photos
	: Tech. Invs (\$) Others
Report Format :	; Weekend (\$)
Lump Sum / I.B.I: (\$ 1500 )	TOTAL

#### COMFORT TRANSPORTATION PTE LTD

#### REPAIR ESTIMATE

Vehicle No.: SHA8047M

Make

: Toyota

Model : Prius Date: 10/06/2022

Insurance: NTUC

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Туре	Unit Price		Amount
1	REAR BUMPER			\$	503.04
10	REAR BUMPER CLIPS			\$	22.00
1	REAR BUMPER TOWING COVER			\$	
1	REAR BUMPER REINFORCEMENT			\$	82.70 378.32
1	REAR BUMPER LOWER COVER			\$	654.96
1	REAR BUMPER TOWING COVER			\$	82.70
	SUB TOTAL			\$	1,723.72
	LESS 25%			\$	430.93
	DISCOUNTED TOTAL			\$	1,292.79
	REAR BUMPER ADVERTISEMENT STICKER	gerbaj Ag		\$	50.00
	REAR BUMPER REVERSE SENSOR			\$	135.70
	REAR BUMPER RUBBER MAT			\$	50.00
				\$	185.70
	Labour Charge				
	PANEL BEATING			\$	400.00
	SPRAY PAINTING CHARGE			\$	300.00
	REMOVE/ REFIX REVERSE SENSOR			\$	60.00
	TOTAL LABOUR			\$	760.00
				Ψ	700.00
	ESTIMATE TOTAL			\$	2,238.49

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Thurn 872357691 10/6/27 1600 1655 LIS 2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

# COMFORTDELGRO ENGINEERING

VEHICLE I	SHA8047M	TYPE OF C:	TP
	NTUC	SURVEY B':	LKK. Thevan
***************************************	305519281	DATE :	16/06/2022

## SUPPLEMENTARY OF PARTS AND LABOUR COSTS

DESCRIPTION	QTY	ESTIMAT	E \$	REMARKS
REAR FENDER ADVERTISEMENT STICKER LH	1	NETT	\$100.00	nic
REAR FENDER ADVERTISEMENT STICKER RH	1	NETT	\$100.00	NCC
		4		
	-	MODA!	The same of the sa	Market Committee Com
THE RESIDENCE OF THE PROPERTY	1	TOTAL	\$200.00	



### ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701 Mainline + 65 6383 6280 Facsimile + 65 6280 9755

Workshops 205 Braddell Road Singapore 579701 59 Loyang Drive Singapore 508969 383 Sin Ming Drive Singapore 575717

Date/Time: 10.06.2022 16:02

Page : 1

Team:

ARC Repair TP(CFSO)1

JOB DESCRIPTION

JOB CARD Sales Order: 4272564

REGN NO.: SHA8047M

JC NO.305519281

MILEAGE

FUEL

STOMER

\_. (R)

(P)

VMS

CITYCAB PTE LTD

STOMER NO. /ULGG / ORIVE Singapore SINGAPORE 575717

65551188

TOYOTA E.....1/2. PRIUS HYBRID(G4)10. DATE/TIME IN 06.2022 14:15

YR OF MANU. 31.05.2017

TARGET DATE

CHASSIS CODE JTDKB3FU403556986

COMPLETION DATE/TIME:


COUNT CARD NO.

Accident Date: 10.06.2022 NATURE: 3P 10.06.2022'

S/NO

LABOR CODE

DESCRIPTION



			LEFT SIDE	RIGHT SIDE
			REAR	

K	ED	&	PA	SSI	ED	OL	IT	BY	

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

ledgement Slip

Vo.:

SHA8047M

Exit Pass

Vehicle No.:

SHA8047M

Service Advisor

Signature/Date

Name of Service Advisor

Date

urned to Service Reception upon collection

To be kept by Security Guard

Our Job Ref No :	305519281			COMFORTDELGRO
Date :	14/06/22			ComfortDelGro Engineering Pte Ltd 59 Loyang Drive Singapore 508969 Fax: 6546 8156
FINALIZATION FORM				Fax: 6546 8156
To :	LKK		_	ax:
Attn : Mr			-	ax .
Vehicle Reg No. : SH	IA8047M	100		40.00.000
				10.06.2022
	of the repairs of the above-	nentioned vel	nicle are as fo	ollows:-
<ol> <li>The repair job shall</li> </ol>	bill to:	NTUC		SMQ5119R
<ol><li>The finalized amour</li></ol>	nt shall be:			
(a) Spare Parts a	after List discount			
(b) Labour Charg	jes			
Total for Part	t-By-Part Repair Cost			\$0.00
Total for Lump	pair (if applicable) osum repair cost after Less: um Repair cost	20	%	\$15:00.00
				<b>413</b> 100.00
Estimated normal per	A CONTRACTOR OF THE PARTY OF TH		vorking days.	
7 working days	bove amount as Correct ar	d Confirmed	if there is n	o reply from you within
Thank you for your as	ssistance.	V	Ve confirm th nalized amou	e estimates and int
Signature :	1			2
Name : Ms. Loke	YY		ignature: ame :	
Tel : 6214835	55	~ <u> </u>	ate :	
Fax : 6546815	6		ate	
Official Use Only		7		-
Item	Amount	Document Attached Yes or No	Confirm By (Signature)	
Rental Rate P/Day	(All productions of the contract of the contra	YES	S ASSOCIATION	
oss of Income Paid		NO	Nacional Espain	
Survey Fees				
TA Search Fee Medical Fees (on behalf of driver, if applicable)	\$7.49 / \$2.00			

Remarks: