



ESTABLISHED 1984

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

**DAMAGE ASSESSMENT REPORT**

INCOME INSURANCE LTD

Ref: CS/INC22008009/Ucy3e2

73 BRAS BASAH ROAD  
#05-01 NTUC TRADE UNION HOUSESINGAPORE  
189556

Date: 19/09/2022

ATTN: CHRYLLIS QUAH

Code: INC

**1. Policy Particulars :- THIRD PARTY CLAIM**

<b>Insured Veh.</b>	FBQ 3112C	<b>Veh. Inspected</b>	SKQ 7854L
<b>Policy No.</b>		<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	MT/1180713-001	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	ANNIE KOH	<b>Assign Date</b>	22/08/2022

**2. Vehicle Particulars & Condition**

<b>Make &amp; Model</b>	TOYOTA WISH (A)	<b>c.c</b>	1798
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2014
<b>Chassis No.</b>	JTDGG20W10J001954	<b>Colour</b>	BEIGE
<b>Odometer</b>	130465 KM	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM
<b>General</b>	GOOD		

**3. Conditions of Tyres**

	Size	Make	Balance
<b>R/H Front Tyre</b>	195/65 R15	YOKOHAMA	6 mm
<b>L/H Front Tyre</b>	195/65 R15	YOKOHAMA	6 mm
<b>R/H Rear Tyre</b>	195/65 R15	YOKOHAMA	6 mm
<b>L/H Rear Tyre</b>	195/65 R15	YOKOHAMA	6 mm

**4. Description of Damages**

THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.  
DAMAGES SEE DETAILS.

**5. General Information**

<b>Accident Date</b>	16/07/2022	<b>Inspect Date / Time</b>	22/08/2022 ( 11:00 AM )
<b>Survey held at</b>	SPECIALISTS MOTOR PTE LTD BLK 3018A UBI ROAD 1 #01-24-26 SINGAPORE 408711		

**5a. Remarks**

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

**5b. Estimate Days of Repair**

<b>ESTIMATED NORMAL PERIOD FOR REPAIR:</b>	<b>3 Working Days</b>
--------------------------------------------	-----------------------