

TSL Auto Garage

TP A16.
Celine.

Estimate

PAGE : 1/2

YEAR : 2018 VEHICLE NO : SLZ3734S
MODEL : MITSUBISHI ATTRAGE 1.2 CVT CHASSIS NO : MMBSTA13AJH001745

Third Party Claims

S/NO	ITEMS	Qty	Price
1	FRONT BUMPER Distorted.	1	\$1,120.00
2	FRONT BUMPER SIDE RETAINER RH. Dmgd	2	\$119.00
3	FRONT BUMPER FOG LAMP RH Crushed	1	\$330.00
4	FRONT BUMPER FOG LAMP COVER RH Missing	1	\$190.00
5	FRONT BUMPER LOWER SKIRTING Detached	1	\$790.00
6	FRONT BUMPER REINFORCEMENT New	1	\$390.00
7	FRONT BUMPER SPONGE New	1	\$190.00
8	FRONT HEADLAMP RH Crushed.	1	\$690.00
9	FRONT HEADLAMP LOWER BRACKET RH New	1	\$100.00
10	FRONT SUPPORT PANEL Gap	1	\$890.00
11	FRONT HEADLAMP PANEL RH Gap	1	\$320.00
12	FRONT FENDER RH Dented.	1	\$390.00
13	FRONT FENDER INNER SHIELD RH Torn	1	\$295.00
14	FRONT FENDER EMBLEM RH New	1	\$110.00
15	FRONT BONNET Gap	1	\$890.00
16	FRONT BONNET HINGE RH Gap	1	\$120.00
17	FRONT SPOT RIMS RH dit	1	\$990.00
18	FRONT LOWER ARM RH	1	\$390.00
19	FRONT WHEEL HUB RH	1	\$520.00
20	FRONT WHEEL HUB BEARING RH Gap	1	\$320.00
21	FRONT WHEEL HUB KNUCKLE RH New 2561	1	\$490.00
22	FRONT STEERING ROD RH	1	\$190.00
23	FRONT STEERING SHAFT RH 2304.90	1	\$490.00

S.N: 930

		Discount 10%	\$1,032.40
		TOTAL :	\$9,291.60
S/NO	SPECIAL ITEMS	Qty	Price
1	FRONT BUMPER CLIPS New	1	\$50.00
2	FRONT FENDER INNER SHIELD CLIPS New	1	\$50.00
3	FRONT TYRE RH New	1	\$400.00
4	FRONT BUMPER LOWER SKIRTING - SIDE Detached New	1	\$400.00
			\$900.00
		Parts Total :	\$9,291.60
		S/P Item :	\$900.00
		TOTAL :	\$10,191.60

60

TSL Auto Garage

Estimate

PAGE : 2/2

YEAR : 2018 VEHICLE NO : SLZ3734S
MODEL : MITSUBISHI ATTRAGE 1.2 CVT CHASSIS NO : MMBSTA13AJH001745

S/NO	LABOURS	AMOUNT
1	To straighten and panel beat front frame members, to cut/weld and remove and refit above parts.	\$ 2,000.00
2	To putty, re-spray painting and polish front affected areas.	\$ 2,000.00
3	To rust proof affected areas.	\$ 100.00
4	To check and rectify wiring.	\$ 100.00
5	To remove and refit front undercarriage assy.	\$ 300.00
6	To conduct wheel alignment.	\$ 100.00
7	To conduct diagnostic systems and to clear faults code.	\$ 200.00
8		

500
600
40
30
x
80
x

NOTE: ALL QUOTED PRICE IS SUBJECT TO 7% GST

TOTAL : \$ 4,800.00
PARTS TOTAL : \$ 10,191.60
GRAND TOTAL : \$ 14,991.60

total: 4544.80
c/s: 3.6k ✓
04 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: