

趙源摩托 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: Allianz Global Corporate & Specialty SE, Singapore Branch

Accident Date : 16.08.2022

Not Authorised
LLP &
Running After Paying
6 days Ex @ 600

Policy No: SP2000683922

Date: 18.08.2022

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货名 DESCRIPTION	单价 Unit Price	银 Amount 额 \$ cts.
Estimate Cost Of Repair To "Subaru Forestor XV" Reg. No SLJ4610T			
1pc	Bonnet		R ₁ 540.00 ✓
2pcs	Bonnet Hinges	36.00	d/n 72.00 L+
1pc	Bonnet Lock		R 90.00 A
1pc	Grille		CM 110.00 —
1pc	Grille Emblem		RM 85.00 —
1pc	Grille Chrome Surround Moulding		RM 220.00 —
1pc	Grille Top Chrome		RM 160.00 —
1pc	Grille Bracket Base		CM 85.00 —
2pcs	Headlamps	480.00	960.00 —
2pcs	Headlamp Side Brackets	25.00	50.00 ?
1pc	Front Bumper		CM 300.00 —
16pcs	Front Bumper Clips	1.50	RM 24.00 —
1pc	Front Bumper Bracket RH		17.00 ?
1pc	Front Bumper Sponge		50.00 ?
1pc	Front Bumper Top Beam		R ₁ 170.00 ✓
2pcs	Front Bumper Top Retainers	10.00	20.00 ?
1pc	Front Bumper Reinforcement		270.00 ?
1pc	Front Bumper Tow Point Cover		RM 10.00 —
1pc	Front Bumper Lower Core		150.00 ?
1pc	Support Panel		RM 520.00 —
2pcs	Support Panel Side Sponges	34.00	68.00 ?
1pc	Radiator		My Ar 820.00 —
1pc	Air Con Condenser		720.00 ?
1pc	Air Cleaner Cold Air Intake Duct		CM 85.00 —
Cost Plus 10%			5,596.00
			559.60
			6,155.60
To Conduct Electrical Check, Focus Headlamp			30.00 20
To Remove / Refit Air Con Condenser & Refill Air Con Gas			100.00 ✓
To Remove / Refit, Radiator System, Bleed & Refill Coolant			50.00 ✓
Labour Charge - Panel Beating, Repairing of Front Chassis, Front O/S Fender, Cnt, Weld Support Panel & Part Replacement			800.00 600
To Respray Affected Areas			950.00 800
Total :			8,085.60

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Signature: