

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	LONPAC INSURAN	NCE BHD	Re	ef:	CS3/LPC22008045/Tqy3e2	
	300 BEACH ROAD #17-04/07 THE CO	NCOURSESINGAPORE 199555	Da	ate:	02/12/2022	
			Co	ode:	LPC2	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	GBA 6745R	Veh. Inspected		GBD 6085X	
	Policy No.	Z22VC05012422	Coverage (\$)		0.00	
	Claim No.	22/22/22/VC05/026170	Excess (\$)		0.00	
	Assign From	ENG HUEY NI	Assign Date		22/08/2022	
2. Vehicle Particulars & Condition						
	Make & Model	NISSAN NV200	c.c		1597	
	Engine No.	HIDDEN	Year of Reg.		2015	
	Chassis No.	VM20058735	Colour		GREY	
	Odometer	185007 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		NIL	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	175/70 R14	ROADKING		6 mm	
	L/H Front Tyre	175/70 R14	ROADKING		6 mm	
	R/H Rear Tyre	175/70 R14	ROADKING		6 mm	
	L/H Rear Tyre	175/70 R14	ROADKING		6 mm	
4.						
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	18/08/2022	Inspection Date		23/08/2022	
	Survey held at	at 2 KAKI BUKIT AVENUE 2 #02-31 KAKI BUKIT AUTOHUB				
	Repairer	Repairer CHENG CHUAN MOTOR SERVICES				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 10 Working Days					