LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd. From: LKK Auto Consultants Pte Ltd

AIG Building, 78 Shenton Way

#09-16

Attn:

Singapore 079120

Azlan, Syazairdina

51 Ubi Ave 1 #01-25

Paya Ubi Industrial Park Singapore 408933

Date: 24 Aug 2022

Preliminary Advice

 Vehicle No
 : SLD9374Z
 Accident Date
 : 18/08/2022

 Make
 : AUDI A4
 Policy No.
 : 2100470586-06

Assignment Date : 23/08/2022 Excess : \$\,\text{S}\,0.00 \)
Date of Inspection : 22/08/2022 Est. Duration of Repair : 10

Inspection At : 24 BENOI SECTOR

REPAIRER: PREMIUM AUTOMOBILES PTE LTD

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	36,974.00
Revised Amount	:S\$	21,938.00
Check Items (Estimated)	:S\$	8,753.00
Total	:S\$	21,938.00
Lump Sum Repair	:S\$	30,691.00

Total Loss Consideration

New for Old Value	:S\$
-------------------	------

Pre-Accident Value :S\$ 82,000.00 COE / PARF Rebate :S\$ 40,833.00

Salvage Value :S\$

Margin for Repair :S\$ 41,167.00

Remarks

(X)	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage.
	Kindly let us have your authorisation.

^() The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

⁽ X) Other comments : Please note that the preliminary advise amount (Revised & Check items) stated are subject to consistency check, part prices and labour cost.